

**FORM  
INSP**Rev  
X/15**State of Colorado  
Oil and Gas Conservation Commission**1120 Lincoln Street, Suite 801, Denver, Colorado 80203  
Phone: (303) 894-2100 Fax: (303) 894-2109

Inspection Date:

05/20/2019

Submitted Date:

05/20/2019

Document Number:

690003576**FIELD INSPECTION FORM**
 Loc ID 336203 Inspector Name: Carlile, Craig On-Site Inspection ☐ 2A Doc Num:                     
**Operator Information:**OGCC Operator Number: 47120Name of Operator: KERR MCGEE OIL & GAS ONSHORE LPAddress: P O BOX 173779City: DENVER State: CO Zip: 80217-**Status Summary:**

- ☐ THIS IS A FOLLOW UP INSPECTION
- ☐ FOLLOW UP INSPECTION REQUIRED
- ☒ NO FOLLOW UP INSPECTION REQUIRED

**Findings:**2 Number of Comments0 Number of Corrective Actions☐ Corrective Action Response Requested**ANY CORRECTIVE ACTION(S) FROM  
PREVIOUS INSPECTIONS THAT HAVE NOT  
BEEN ADDRESSED ARE STILL APPLICABLE****Contact Information:**

Contact Name	Phone	Email	Comment
, Inspections		COGCCinspections@Anadarko.com	<a href="#">All Inspections</a>

**Inspected Facilities:**

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
287496	WELL	PR	01/01/2019	OW	123-24351	REYNOLDS 1-23	PA
289542	WELL	PR	01/01/2019	OW	123-24874	REYNOLDS 27-23X	PA

**General Comment:**

**Location**Overall Good: ☒

Emergency Contact Number:

Comment: Corrective Action: Date: Overall Good: ☒**Spills:**

Type	Area	Volume		
------	------	--------	--	--

In Containment: No

Comment: ☐ Multiple Spills and Releases?**Equipment:**

corrective date

Type: Plunger Lift	# 0		
Comment:			
Corrective Action:			Date:
Type: Horizontal Separator	# 0		
Comment:			
Corrective Action:			Date:
Type: Horizontal Heated Separator	# 0		
Comment:			
Corrective Action:			Date:
Type: LACT	# 0		
Comment:			
Corrective Action:			Date:
Type: Compressor	# 0		
Comment:			
Corrective Action:			Date:
Type: Emission Control Device	# 0		
Comment:			
Corrective Action:			Date:
Type: Gas Meter Run	# 0		
Comment:			
Corrective Action:			Date:
Type: Vertical Separator	# 0		
Comment:			
Corrective Action:			Date:

**Tanks and Berms:**

Contents	#	Capacity	Type	Tank ID	SE GPS
CRUDE OIL	0				,

Comment:		
Corrective Action:		Date:

Paint

Condition		
Other (Content)		
Other (Capacity)		
Other (Type)		

Berms

Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance
Comment:				
Corrective Action:				Date:

Contents	#	Capacity	Type	Tank ID	SE GPS
PRODUCED WATER	0				,

Comment:		
Corrective Action:		Date:

Paint

Condition		
Other (Content)		
Other (Capacity)		
Other (Type)		

Berms

Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance
Comment:				
Corrective Action:				Date:

Venting:

Yes/No		
Comment:		
Corrective Action:		Date:

Flaring:

Type		
Comment:		
Corrective Action:		Date:

**Inspected Facilities**

Facility ID: 287496	Type: WELL	API Number: 123-24351	Status: PR	Insp. Status: PA
---------------------	------------	-----------------------	------------	------------------

Facility ID: 289542	Type: WELL	API Number: 123-24874	Status: PR	Insp. Status: PA
---------------------	------------	-----------------------	------------	------------------

**COGCC Comments**

Comment	User	Date
<p>On Monday, May 20, 2019 at 10:48, I, Craig Carlile conducted an on-site inspection at: 336203, REYNOLDS-63N68W 23NENE Operated by: Anadarko</p> <p>While there I observed: Former location. All wells have been plugged. New location has been established with a new location number.</p> <p>Weather: Overcast, cold, rain</p> <p>Possible compliance issues observed: None: ?</p> <p>This is a summary of the inspection report.</p>	carlilec	05/20/2019

**Attached Documents**

You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
690003577	Photo	<a href="http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4826848">http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4826848</a>