

**FORM
INSP**Rev
X/15**State of Colorado
Oil and Gas Conservation Commission**1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109

Inspection Date:

05/20/2019

Submitted Date:

05/20/2019

Document Number:

690003578**FIELD INSPECTION FORM**

Loc ID 436446 Inspector Name: Carlile, Craig On-Site Inspection ☐ 2A Doc Num: _____

Operator Information:OGCC Operator Number: 47120Name of Operator: KERR MCGEE OIL & GAS ONSHORE LPAddress: P O BOX 173779City: DENVER State: CO Zip: 80217-**Status Summary:**

- ☐ THIS IS A FOLLOW UP INSPECTION
☐ FOLLOW UP INSPECTION REQUIRED
☒ NO FOLLOW UP INSPECTION REQUIRED

Findings:9 Number of Comments0 Number of Corrective Actions☐ Corrective Action Response Requested**ANY CORRECTIVE ACTION(S) FROM
PREVIOUS INSPECTIONS THAT HAVE NOT
BEEN ADDRESSED ARE STILL APPLICABLE****Contact Information:**

Contact Name	Phone	Email	Comment
, Inspections		COGCCinspections@Anadarko.com	All Inspections

Inspected Facilities:

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
436443	WELL	PR	10/01/2018	OW	123-39131	REYNOLDS CATTLE 3N-19HZ	PR
436444	WELL	SI	10/01/2017	OW	123-39132	REYNOLDS CATTLE 3C-19HZ	SI
436445	WELL	PR	11/01/2017	OW	123-39133	REYNOLDS CATTLE 31C-23HZ	PR
436448	WELL	PR	10/01/2018	OW	123-39135	REYNOLDS CATTLE 30N-23HZ	PR
436449	WELL	PR	12/17/2014	OW	123-39136	REYNOLDS CATTLE 31N-23HZ	PR
436450	WELL	PR	10/01/2018	OW	123-39137	REYNOLDS CATTLE 28N-19HZ	PR

General Comment:

LocationOverall Good: ☒

Signs/Marker:			
Type	WELLHEAD		
Comment:			
Corrective Action:		Date:	

Emergency Contact Number:

Comment:

Corrective Action: Date:

Overall Good: ☒

Spills:					
Type	Area	Volume			

In Containment: No

Comment: ☐ Multiple Spills and Releases?

Fencing/:			
Type	WELLHEAD		
Comment:			
Corrective Action:		Date:	

Equipment:			corrective date
Type: Pump Jack	# 1		
Comment:			
Corrective Action:		Date:	
Type: Plunger Lift	# 5		
Comment:			
Corrective Action:		Date:	

Tanks and Berms:

Contents	#	Capacity	Type	Tank ID	SE GPS
			CENTRALIZED BATTERY		40.216940,-104.964600
Comment:	Shared batter services.				
Corrective Action:				Date:	

Paint

Condition	
Other (Content)	
Other (Capacity)	
Other (Type)	

Berms

Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance

Inspected Facilities

Facility ID: 436443 Type: WELL API Number: 123-39131 Status: PR Insp. Status: PR

Producing WellComment: PR

Corrective Action:

Date:

Facility ID: 436444 Type: WELL API Number: 123-39132 Status: SI Insp. Status: SI

Idle WellPurpose: ☒ Shut In☐ Temporarily Abandoned

Reminder: _____

Comment: si

Corrective Action:

Date: _____

Facility ID: 436445 Type: WELL API Number: 123-39133 Status: PR Insp. Status: PR

Producing WellComment: PR

Corrective Action:

Date:

Facility ID: 436448 Type: WELL API Number: 123-39135 Status: PR Insp. Status: PR

Producing WellComment: PR

Corrective Action:

Date:

Facility ID: 436449 Type: WELL API Number: 123-39136 Status: PR Insp. Status: PR

Producing WellComment: PR

Corrective Action:

Date:

Facility ID: 436450 Type: WELL API Number: 123-39137 Status: PR Insp. Status: PR

Producing WellComment: PR

Corrective Action:

Date:

Reclamation - Storm Water - Pit**Storm Water:**

Loc Erosion BMPs	BMP Maintenance	Lease Road Erosion BMPs	Lease BMP Maintenance	Chemical BMPs	Chemical BMP Maintenance	Comment
Gravel	Pass					

Comment: Corrective Action: Date: **Pits:** ☒ NO SURFACE INDICATION OF PIT**COGCC Comments**

Comment	User	Date
On Monday, May 20, 2019 at 12:16, I, Craig Carlile conducted an on-site inspection at: 436446 Operated by: Anadarko While there I observed: 6 Wells, 5 Plunger Lift and 1 Pump Jack Weather: Overcast, cold, rain Possible compliance issues observed: None: ? This is a summary of the inspection report.	carlilec	05/20/2019

Attached DocumentsYou can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
690003579	Photos	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4826983