

**FORM
INSP**Rev
X/15**State of Colorado
Oil and Gas Conservation Commission**1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109

Inspection Date:

05/17/2019

Submitted Date:

05/20/2019

Document Number:

694400168**FIELD INSPECTION FORM**

Loc ID 451448 Inspector Name: Kraich, Adam On-Site Inspection ☐ 2A Doc Num: _____

Operator Information:OGCC Operator Number: 10110Name of Operator: GREAT WESTERN OPERATING COMPANY LLCAddress: 1001 17TH STREET #2000City: DENVER State: CO Zip: 80202**Status Summary:**

- ☐ THIS IS A FOLLOW UP INSPECTION
- ☐ FOLLOW UP INSPECTION REQUIRED
- ☐ NO FOLLOW UP INSPECTION REQUIRED

Findings:3 Number of Comments0 Number of Corrective Actions☐ Corrective Action Response Requested**ANY CORRECTIVE ACTION(S) FROM
PREVIOUS INSPECTIONS THAT HAVE NOT
BEEN ADDRESSED ARE STILL APPLICABLE****Contact Information:**

Contact Name	Phone	Email	Comment
,		cogccinspections@gwogco.com	All Inspections

Inspected Facilities:

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
451448	LOCATION	AC	07/22/2017		-	Raindance Offsite Completions Pad	AC

General Comment:

Inspected Facilities

Facility ID: 451448 Type: LOCATION API Number: - Status: AC Insp. Status: AC

Producing Well

Comment: AC

Corrective Action:

Date:

COGCC Comments

Comment	User	Date
<p>COGCC Inspection Report Summary</p> <p>This inspection was performed in response to COGCC complaint #200447309, and 200447307. Please see document#694400165 for complaint details and response. On 5/16/2019 at approximately 13:50, I, Supervisor Adam Kraich, conducted an on-site inspection at the Raindance off site pad, owned and operated by Great Western Oil & Gas. at location ID 451448, in Weld County Colorado.</p> <p>While there, I observed an abandoned off site stimulation location. Only fresh water infrastructure remains on the location, along with sound wall equipment. Interim reclamation has yet to begin on the location.</p> <p>No odors were observed on location during my inspection, using CDPHE Reg. 2 detection method. Weather conditions were; overcast with wind speeds observed as being mostly calm with a light breeze out of the northeast.</p> <p>No Violation of COGCC rules were observed at time of inspection.</p> <p>This is a summary of inspection report.</p>	kraicha	05/20/2019

Attached DocumentsYou can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
694400169	Inspection Photos	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4827185