

Inspection Photos
Location Name: DNR-Hartman State #11-16
Location ID: 320317



Pic 1



Pic 2

Inspection Photos
Location Name: DNR-Hartman State #11-16
Location ID: 320317



Pic 3 no netting around produced water pit



Pic 4

Inspection Photos
Location Name: DNR-Hartman State #11-16
Location ID: 320317



Pic 5 stained soil near wellhead



Pic 6 stained soil near wellhead

Inspection Photos
Location Name: DNR-Hartman State #11-16
Location ID: 320317



Pic 7 polish rod is bent, no horses head on pumping unit



Pic 8 secondary containment in motor house appears to be close to overflowing.