

Inspection Photos

Operator: Maralex Resources
Location/API #: 067-09612
Date: 5-14-2019



Photo 1. View of the southern project area from the southeastern corner facing westward.



Photo 2. View of musk thistles in foreground and background, within the southern project area.



Photo 3. View of Russian knapweed (*Rhaponticum repens*) within the interim reclamation area.



Photo 4. View of pit liner debris and ponding area within the northeastern project area.



Photo 5. View of concrete debris within piles of liner debris.