

Inspection Photos
Operator: Maralex Resources
Location/API #: 067-09474
Date: 5-14-2019



Photo 1. View of the southwestern project area from the northwestern corner facing southeastward. Revegetation is progressing within the interim reclamation area.



Photo 2. View of wood debris piles within the southern corner of the project area.



Photo 3. View of unused equipment within the eastern project area.



Photo 4. View of waste and debris within the interim reclamation area.