

Inspection Photos
Location Name: Amoco-Federal 20-9
API: 05-081-06516



Photo 1. Overview of location taken at entrance facing east.

Inspection Photos
Location Name: Amoco-Federal 20-9
API: 05-081-06516



Photo 2. Stained soil at pump jack motor.



Photo 3. Stained soil at wellhead.

Inspection Photos
Location Name: Amoco-Federal 20-9
API: 05-081-06516



Photo 4. Concrete base stored on location.



Photo 5. Pit.