

**FORM
INSP**Rev
X/15**State of Colorado
Oil and Gas Conservation Commission**1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109

Inspection Date:

05/21/2019

Submitted Date:

05/21/2019

Document Number:

679704153**FIELD INSPECTION FORM**

Loc ID 429335	Inspector Name: Moran, Rick	On-Site Inspection <input type="checkbox"/>	2A Doc Num: _____	Status Summary: <input checked="" type="checkbox"/> THIS IS A FOLLOW UP INSPECTION <input checked="" type="checkbox"/> FOLLOW UP INSPECTION REQUIRED <input type="checkbox"/> NO FOLLOW UP INSPECTION REQUIRED Findings: 10 Number of Comments 3 Number of Corrective Actions <input checked="" type="checkbox"/> Corrective Action Response Requested
Operator Information: OGCC Operator Number: <u>6720</u> Name of Operator: <u>ROBERT L BAYLESS PRODUCER LLC</u> Address: <u>621 17TH ST STE 2300</u> City: <u>DENVER</u> State: <u>CO</u> Zip: <u>80293</u>				ANY CORRECTIVE ACTION(S) FROM PREVIOUS INSPECTIONS THAT HAVE NOT BEEN ADDRESSED ARE STILL APPLICABLE

Contact Information:

Contact Name	Phone	Email	Comment
Trujillo, Helen		notices@rlbayless.com	All inspections
Kellerby, Shaun	970-712-1248	shaun.kellerby@state.co.us	

Inspected Facilities:

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
429384	WELL	PR	09/12/2013	OW	103-11932	WEAVER RIDGE 14-15H	PR
452292	WELL	DG	05/03/2018		103-12290	Weaver Ridge 14-15H2	TA

General Comment:[COGCC Inspection Report Summary.](#)

On 5/21/2019 at approximately 11:30, inspector Rick Moran, conducted a follow up inspection at Robert L Bayless Producer's well Weaver Ridge 14-15H in Rio Blanco county of FIR document 679702488.

The following compliance issues were identified as resolved:

- 1) Tank capacity.

Additional compliance issues were identified:

- 1) Oily waste at pump jack. Photo 2. Complete by 6-21-2019.
- 2) Oil on tank liner by truck off loading valves. Photo 3. Complete by 6-21-2019.
- 3) Container without label at pump jack. Photo 4. Complete by 7-19-2019.

A follow up on this site inspection will be conducted to ensure the compliance issues have been corrected to comply with COGCC rules.

This is a summary of inspection report 679704153.

LocationOverall Good: ☒

Signs/Marker:			
Type	BATTERY		
Comment:			
Corrective Action:		Date:	
Type	WELLHEAD		
Comment:			
Corrective Action:		Date:	
Type	CONTAINERS		
Comment:	Container at pump jack without label.		
Corrective Action:	Install sign to comply with Rule 210.d.	Date:	07/19/2019
Type	TANK LABELS/PLACARDS		
Comment:			
Corrective Action:		Date:	

Emergency Contact Number:

Comment: 505-327-0880

Corrective Action:

Date: _____

Good Housekeeping:

Type	OTHER		
Comment:	Oil on tank liner by truck off loading valves.		
Corrective Action:	Properly treat or dispose of oily waste in accordance with 907.e.	Date:	06/21/2019
Type	OTHER		
Comment:	Oily waste on ground at pump jack by engine exhaust.		
Corrective Action:	Properly treat or dispose of oily waste in accordance with 907.e.	Date:	06/21/2019

Overall Good: ☐

Spills:			
Type	Area	Volume	

In Containment: No

Comment:

☐ Multiple Spills and Releases?

Equipment:			corrective date
Type: Deadman # & Marked	# 4		
Comment:			
Corrective Action:		Date:	
Type: Pump Jack	# 1		
Comment:			
Corrective Action:		Date:	

Type: Gas Meter Run	# 1		
Comment:			
Corrective Action:			Date:
Type: Horizontal Heated Separator	# 1		
Comment:			
Corrective Action:			Date:
Type: Bird Protectors	# 1		
Comment:			
Corrective Action:			Date:
Type: Ancillary equipment	# 1		
Comment:	Container of motor oil with secondary containment.		
Corrective Action:			Date:
Type: Emission Control Device	# 1		
Comment:			
Corrective Action:			Date:

Tanks and Berms:

Contents	#	Capacity	Type	Tank ID	SE GPS	
CRUDE OIL	4	400 BBLs	STEEL AST		39.954130,-109.032630	
Comment:						
Corrective Action:						Date:

Paint

Condition	Adequate	
Other (Content)		
Other (Capacity)		
Other (Type)		

Berms

Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance
Metal	Adequate	Walls Sufficient	Base Sufficient	Adequate
Comment:				
Corrective Action:				
	Date:			

Venting:

Yes/No	NO	
Comment:		
Corrective Action:	Date:	

Flaring:

Type	
Comment:	
Corrective Action:	Date:

Inspected FacilitiesFacility ID: 429384 Type: WELL API Number: 103-11932 Status: PR Insp. Status: PR**Producing Well**Comment: Pump jack producing at time of inspection.

Corrective Action:

Date:

Facility ID: 452292 Type: WELL API Number: 103-12290 Status: DG Insp. Status: TA**Idle Well**Purpose: ☐ Shut In ☒ Temporarily Abandoned

Reminder: _____

Comment: Well not attached to flow line.

Corrective Action:

Date: _____

Reclamation - Storm Water - Pit**Storm Water:**

Loc Erosion BMPs	BMP Maintenance	Lease Road Erosion BMPs	Lease BMP Maintenance	Chemical BMPs	Chemical BMP Maintenance	Comment

Comment: [No apparent soil migration, erosion, or soil movement on location.](#)

Corrective Action:

Date: _____

Pits: ☒ NO SURFACE INDICATION OF PIT

Attached Documents

You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
679704154	inspection photos	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4829252