

Location

Overall Good:

Signs/Marker:

Type	BATTERY		
Comment:			
Corrective Action:		Date:	
Type	TANK LABELS/PLACARDS		
Comment:			
Corrective Action:		Date:	

Emergency Contact Number:

Comment:

Corrective Action: Date: _____

Overall Good:

Spills:

Type	Area	Volume		

In Containment: No

Comment:

Multiple Spills and Releases?

Tanks and Berms:

Contents	#	Capacity	Type	Tank ID	SE GPS
CRUDE OIL	1	300 BBLS	STEEL AST		40.382890,-105.064670
Comment:	<input type="text"/>				
Corrective Action:	<input type="text"/>				Date: <input type="text"/>

Paint

Condition	<input type="text"/>
Other (Content)	<input type="text"/>
Other (Capacity)	<input type="text"/>
Other (Type)	<input type="text"/>

Berms

Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance
Metal	Adequate	Walls Sufficient	Base Sufficient	Adequate
Comment:	<input type="text"/>			
Corrective Action:	<input type="text"/>			Date: <input type="text"/>

Venting:

Yes/No	<input type="text"/>	
Comment:	<input type="text"/>	
Corrective Action:	<input type="text"/>	Date: <input type="text"/>

Flaring:

Type	<input type="text"/>
------	----------------------

Comment:		
Corrective Action:		Date:

Inspected Facilities

Facility ID: 445408 Type: TANK API Number: - Status: AC Insp. Status: AO

COGCC Comments

Comment	User	Date
<p>On Wednesday, May 22, 2019 at 08:41, I, Craig Carlile conducted an on-site inspection at: 445408 PROSPECT LAND CO.-65N69W 24NWSE Operated by: Magpie While there I observed: Tank Battery Weather: Sunny, ground wet from snow yesterday. Possible compliance issues observed: None This is a summary of the inspection report.</p>	carlilec	05/22/2019

Attached Documents

You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
690003583	Photo	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4829702