

Location

Overall Good:

Signs/Marker:

	Type WELLHEAD		
Comment:			
Corrective Action:			Date:

Emergency Contact Number:

Comment:			
Corrective Action:			Date: _____

Overall Good:

Spills:

Type	Area	Volume			

In Containment: No

Comment: _____

Multiple Spills and Releases?

Fencing/:

	Type WELLHEAD		
Comment:			
Corrective Action:			Date:

Equipment:

					corrective date
Type: Plunger Lift	# 3				
Comment:					
Corrective Action:				Date:	

Tanks and Berms:

Contents	#	Capacity	Type	Tank ID	SE GPS
			CENTRALIZED BATTERY		40.193760,-104.815180
Comment:					
Corrective Action:				Date:	

Paint

Condition					
Other (Content)					
Other (Capacity)					
Other (Type)					

Berms

Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance
Comment:				
Corrective Action:				Date:

Venting:

Yes/No	NO		
Comment:			
Corrective Action:		Date:	

Flaring:

Type			
Comment:			
Corrective Action:		Date:	

Inspected Facilities

Facility ID: 414447 Type: WELL API Number: 123-30747 Status: SI Insp. Status: SI

Idle Well

Purpose: Shut In Temporarily Abandoned Reminder: _____

Comment: Shut in and locked out at the wellhead connection to the flow line.

Corrective Action: _____ Date: _____

Facility ID: 414467 Type: WELL API Number: 123-30757 Status: PR Insp. Status: SI

Idle Well

Purpose: Shut In Temporarily Abandoned Reminder: _____

Comment: Shut in and locked out at the wellhead connection to the flow line.

Corrective Action: _____ Date: _____

Facility ID: 414657 Type: WELL API Number: 123-30817 Status: PR Insp. Status: SI

Idle Well

Purpose: Shut In Temporarily Abandoned Reminder: _____

Comment: Shut in and locked out at the wellhead connection to the flow line.

Corrective Action: _____ Date: _____

COGCC Comments

Comment	User	Date
<p>On Wednesday, May 22, 2019 at 10:19, I, Craig Carlile conducted an on-site inspection at: 414470 MEEKS (L) MULTI WELL 30-18D Operated by: Anadarko While there I observed: Three wells shut in. Weather: Sunny, ground wet from snow yesterday. Possible compliance issues observed: None This is a summary of the inspection report.</p>	carlilec	05/22/2019

Attached Documents

You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
690003587	Photos	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4829704