

Inspection Photos
Location Name: Elaine #43-28
Location ID: 336320



Pic 1 Tank not painted, no placard capacity, open piping not capped



Pic 2 piping not capped on separator

Inspection Photos
Location Name: Elaine #43-28
Location ID: 336320



Pic 3



Pic 4 stained soil under counterweight