

**FORM  
INSP**Rev  
X/15**State of Colorado  
Oil and Gas Conservation Commission**1120 Lincoln Street, Suite 801, Denver, Colorado 80203  
Phone: (303) 894-2100 Fax: (303) 894-2109

Inspection Date:

05/22/2019

Submitted Date:

05/22/2019

Document Number:

693500136**FIELD INSPECTION FORM**
 Loc ID 317973 Inspector Name: Silver, Randy On-Site Inspection ☐ 2A Doc Num: \_\_\_\_\_
**Operator Information:**OGCC Operator Number: 31257Name of Operator: FRITZLER RESOURCES INCAddress: P O BOX 114City: FORT MORGAN State: CO Zip: 80701**Status Summary:**☐ THIS IS A FOLLOW UP INSPECTION☒ FOLLOW UP INSPECTION REQUIRED☐ NO FOLLOW UP INSPECTION REQUIRED**Findings:**18 Number of Comments8 Number of Corrective Actions☒ Corrective Action Response Requested**ANY CORRECTIVE ACTION(S) FROM  
PREVIOUS INSPECTIONS THAT HAVE NOT  
BEEN ADDRESSED ARE STILL APPLICABLE****Contact Information:**

Contact Name	Phone	Email	Comment
Fritzler, Gene	(970) 867-9388	gfritzler@bresnan.net	<a href="#">All Inspections</a>

**Inspected Facilities:**

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
240288	WELL	PR	07/07/1997	GW	123-08076	HOPKINS 41C-19 2	PR

**General Comment:**

**Location**Overall Good: ☒

<b>Signs/Marker:</b>			
Type	TANK LABELS/PLACARDS		
Comment:	Produced water tank missing NFPA placards and tank volume sign.		
Corrective Action:	Install sign to comply with Rule 210.d.	Date:	06/22/2019
Type	BATTERY		
Comment:	Adequate		
Corrective Action:		Date:	
Type	WELLHEAD		
Comment:	Adequate		
Corrective Action:		Date:	

Emergency Contact Number:

Comment:

Corrective Action:

Date: \_\_\_\_\_

**Good Housekeeping:**

Type	OTHER		
Comment:	Stained soil: inside separator house.		
Corrective Action:	Properly treat or dispose of oily waste in accordance with 907.e	Date:	06/22/2019
Type	UNUSED EQUIPMENT		
Comment:	Unused equipment: fiber glass and steel pipe next to separator		
Corrective Action:	Comply with rule 603 f	Date:	06/05/2019
Type	OTHER		
Comment:	Mechanical issue: piping in separator appears to be leaking on ground.		
Corrective Action:	Securely fasten all valves, pipes, and fittings to ensure good mechanical condition, inspect at regular intervals and maintain in good mechanical condition per Rule 605.d.	Date:	06/22/2019
Type	TRASH		
Comment:	Trash on well site and on TNK BTRY location. See Photos		
Corrective Action:	Comply with rule 603 f	Date:	06/05/2019

Overall Good: ☐

<b>Spills:</b>			
Type	Area	Volume	

In Containment: No

Comment:

☐ Multiple Spills and Releases?

<b>Fencing/:</b>			
Type	PUMP JACK		
Comment:	Steel rod		
Corrective Action:		Date:	

<b>Equipment:</b>			corrective date
Type: Bird Protectors	# 1		
Comment:			
Corrective Action:			Date:
Type: Pump Jack	# 1		
Comment:			
Corrective Action:			Date:
Type: Ancillary equipment	# 1		
Comment:	Electric panel		
Corrective Action:			Date:
Type: Bradenhead	# 1		
Comment:	Appears to be plumbed to surface		
Corrective Action:			Date:
Type: Horizontal Heated Separator	# 1		
Comment:			
Corrective Action:			Date:
Type: Prime Mover	# 1		
Comment:	Electric motor		
Corrective Action:			Date:
Type: Plunger Lift	# 0		
Comment:			
Corrective Action:			Date:
Type: Gas Meter Run	# 1		
Comment:			
Corrective Action:			Date:

**Tanks and Berms:**

Contents	#	Capacity	Type	Tank ID	SE GPS
PRODUCED WATER	1				,
Comment:	No NFPA placards or volume sign				
Corrective Action:	Install sign to comply with Rule 210.d.				Date: 06/22/2019

**Paint**

Condition	Adequate	
Other (Content)		
Other (Capacity)		
Other (Type)		

**Berms**

Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance
Comment:	Shares containment with crude oil tank			

Corrective Action:					Date:	
Contents	#	Capacity	Type	Tank ID	SE GPS	
CRUDE OIL	1	300 BBLS	STEEL AST		,	
Comment:						
Corrective Action:					Date:	

**Paint**

Condition	Adequate	
Other (Content)		
Other (Capacity)		
Other (Type)		

**Berms**

Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance	
Earth	Adequate	Walls Sufficient	Base Sufficient	Adequate	
Comment:					
Corrective Action:					Date:

**Venting:**

Yes/No	YES		
Comment:	Pilot appears not to be lit on heater on separator.		
Corrective Action:	Securely fasten all valves, pipes, and fittings to ensure good mechanical condition, inspect at regular intervals and maintain in good mechanical condition per Rule 605.d.	Date:	05/23/2019

**Flaring:**

Type		
Comment:		
Corrective Action:		Date:

Inspected Facilities									
Facility ID:	240288	Type:	WELL	API Number:	123-08076	Status:	PR	Insp. Status:	PR
Producing Well									
Comment:	PR. Power at breaker box is in the off position at time of inspection.								
Corrective Action:								Date:	

**Reclamation - Storm Water - Pit****Storm Water:**

Loc Erosion BMPs	BMP Maintenance	Lease Road Erosion BMPs	Lease BMP Maintenance	Chemical BMPs	Chemical BMP Maintenance	Comment
				Material Handling And Spill Prevention	Fail	
Comment: <u>Storage of chemicals and material</u>						Date: <u>06/05/2019</u>
Corrective Action: <u>Install adequate BMB for storage of materials that could result in the discharges causing pollution of surface waters per rule 1002 f (2) B</u>						
<b>Pits:</b> <input checked="" type="checkbox"/> NO SURFACE INDICATION OF PIT						

**COGCC Comments**

Comment	User	Date
<b>COGCC Inspection Report Summary</b> On Wednesday May 22, 2019 at approximately 1:15PM, I, Inspector Randy Silver Conducted an on-site inspection at a Fritzler Resources site Hopkins 41C-19#2, at API# 05-123-08076 in Weld County Colorado. While there, I observed a Well site and Tank battery. During this inspection the following possible compliance issues were observed: Chemical storage: Rule 1002 f(2) B Corrective action date of (CAD) 6-5-19 See photo 1 Trash: Rule 603 f CAD of 6-5-19 See photos 3,7,9 Signs: Rule 210 d CAD of 6-22-19 See photo 6 Stained soil: Rule 907 e CAD of 6-22-19 See photo 9 Mechanical issue: Rule 605 d CAD of 6-22-19 See photo9 Mechanical issue venting gas: Rule 605 d CAD of 5-23-19 Unused equipment: Rule 603 f Corrective action date of 6-5-19 See photo 10 At time of inspection I observed multiple areas with trash on well site and tank battery location. Improper chemical storage 55 gal drums next to PU. Pilot on separator burner appears to not be lit and is venting. I called emergency contact number at approx.1:15 PM talked to answering service and was informed they would call someone to call me back. MR Fritzler did call me back at 1:53 PM informed me he was on his way to address the issue. Weather conditions: over cast, road and location muddy due to storm event on previous day. A follow up on this site inspection needs to be conducted to ensure the compliance issues have been corrected to comply with COGCC rules. This is a summary of inspection report.	silverr	05/22/2019

**Attached Documents**

You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
693500137	loc pic	<a href="http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4830047">http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4830047</a>