

**FORM  
INSP**

Rev  
X/15

**State of Colorado  
Oil and Gas Conservation Commission**

1120 Lincoln Street, Suite 801, Denver, Colorado 80203  
Phone: (303) 894-2100 Fax: (303) 894-2109



Inspection Date:

05/22/2019

Submitted Date:

05/22/2019

Document Number:

693500138

**FIELD INSPECTION FORM**

Loc ID 318088 Inspector Name: Silver, Randy On-Site Inspection  2A Doc Num: \_\_\_\_\_

**Status Summary:**

- THIS IS A FOLLOW UP INSPECTION
- FOLLOW UP INSPECTION REQUIRED
- NO FOLLOW UP INSPECTION REQUIRED

**Operator Information:**

OGCC Operator Number: 46290  
Name of Operator: KP KAUFFMAN COMPANY INC  
Address: 1675 BROADWAY, STE 2800  
City: DENVER State: CO Zip: 80202

**Findings:**

- 8 Number of Comments
- 2 Number of Corrective Actions
- Corrective Action Response Requested

**ANY CORRECTIVE ACTION(S) FROM PREVIOUS INSPECTIONS THAT HAVE NOT BEEN ADDRESSED ARE STILL APPLICABLE**

**Contact Information:**

Contact Name	Phone	Email	Comment
,		dnr_cogccenforcement@state.co.us	
,		dnr_cogccengineering@state.co.us	
Gillette, Kira		kira.gillette@state.co.us	
Gomez, Jason		jason.gomez@state.co.us	
Lara-Mesa, Susana	303-825-4822	cogcc@kpk.com	<a href="#">All inspections</a>
Canfield, Chris		chris.canfield@state.co.us	
Pesicka, Conor		conor.pesicka@state.co.us	

**Inspected Facilities:**

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
240584	WELL	SI	02/01/2019	OW	123-08372	LAURIDSON 2-A	SI

**General Comment:**

**Location**

Overall Good:

**Signs/Marker:**

Type	WELLHEAD		
Comment:	Adequate		
Corrective Action:		Date:	

Emergency Contact Number:

Comment:		Date:	
Corrective Action:			

**Good Housekeeping:**

Type	UNUSED EQUIPMENT		
Comment:	Unused equipment: floo back tank		
Corrective Action:	Comply with 603 f	Date:	08/22/2019

Overall Good:

**Spills:**

Type	Area	Volume		

In Containment: No

Comment:

Multiple Spills and Releases?

**Fencing/:**

Type			
Comment:			
Corrective Action:		Date:	

**Equipment:**

Type		#		corrective date
Bradenhead		# 1		
Comment:	Appears to be plumbed to surface			
Corrective Action:			Date:	
Ancillary equipment		# 1		
Comment:	Electric panel			
Corrective Action:			Date:	
Prime Mover		# 1		
Comment:	Electric motor			
Corrective Action:			Date:	
Pump Jack		# 1		
Comment:				
Corrective Action:			Date:	

**Venting:**

Yes/No	NO		
Comment:			

Corrective Action:		Date:	
--------------------	--	-------	--

**Flaring:**

Type			
Comment:			
Corrective Action:		Date:	

**Inspected Facilities**

Facility ID: 240584 Type: WELL API Number: 123-08372 Status: SI Insp. Status: SI

**Idle Well**

Purpose:  Shut In  Temporarily Abandoned Reminder: \_\_\_\_\_

Comment: Review of monthly operations records indicate operator is inaccurate in submitting monthly operations reports. Production records indicate well was shut in on Feb of 2019 but still producing oil. Records show production facility has been under construction since September of 2018 Per inspection Doc#688500086.

Corrective Action: **Submit required Form 7(s) to COGCC per rule 309** Date: 06/22/2019

**Reclamation - Storm Water - Pit****Storm Water:**

Loc Erosion BMPs	BMP Maintenance	Lease Road Erosion BMPs	Lease BMP Maintenance	Chemical BMPs	Chemical BMP Maintenance	Comment

Comment: Corrective Action: 

Date: \_\_\_\_\_

**Pits:**  NO SURFACE INDICATION OF PIT**COGCC Comments**

Comment	User	Date
<p>COGCC Inspection Report Summary</p> <p>On Wednesday May 22, 2019 at approximately 2:00PM, I, Inspector Randy Silver Conducted an on-site inspection at a KP Kauffman site Lauridson #2A, at API# 05-123-08372 in Weld County Colorado.</p> <p>While there, I observed a Well site.</p> <p>During this inspection the following possible compliance issues were observed:</p> <p>Production records: Rule 309 Corrective action date of 6-22-19</p> <p>Unused equipment: Rule 603 f Corrective action date of 8-22-19 See photo 3</p> <p>At time of inspection I observed a flow back tank not connected to WH on location. No indication in records of work performed to well. After reviewing production records well is still showing production of oil. Well has been shut in since February of 2019. Production facility #457409 has been under construction since September of 2018 per inspection Doc#688500086. At time of inspection Separator on production facility appears to have all production piping removed. Inlet valves on crude oil tank are closed at time of inspection. Refer to facility inspection for further information. Doc # 693500142</p> <p>Weather conditions: over cast, road and location muddy due to storm event on previous day.</p> <p>A follow up on this site inspection needs to be conducted to ensure the compliance issues have been corrected to comply with COGCC rules.</p> <p>This is a summary of inspection report.</p>	silverr	05/22/2019

**Attached Documents**You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
693500139	loc pic	<a href="http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4830048">http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4830048</a>