

**FORM
INSP**Rev
X/15**State of Colorado
Oil and Gas Conservation Commission**1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109

Inspection Date:

05/14/2019

Submitted Date:

05/14/2019

Document Number:

687904769**FIELD INSPECTION FORM**

Loc ID 311955 Inspector Name: Stewart, Joseph On-Site Inspection ☐ 2A Doc Num: _____

Operator Information:OGCC Operator Number: 53255Name of Operator: MARALEX RESOURCES INCAddress: P O BOX 338City: IGNACIO State: CO Zip: 81137**Status Summary:**☐ THIS IS A FOLLOW UP INSPECTION☒ FOLLOW UP INSPECTION REQUIRED☐ NO FOLLOW UP INSPECTION REQUIRED**Findings:**18 Number of Comments6 Number of Corrective Actions☒ Corrective Action Response Requested**ANY CORRECTIVE ACTION(S) FROM
PREVIOUS INSPECTIONS THAT HAVE NOT
BEEN ADDRESSED ARE STILL APPLICABLE****Contact Information:**

Contact Name	Phone	Email	Comment
,	970-563-4000	maralextech@gmail.com	All Inspections
Labowskie, Steve		steve.labowskie@state.co.us	
Ferrin, Jeremy		jeremy.ferrin@state.co.us	

Inspected Facilities:

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
277814	WELL	PR	01/11/2006	GW	067-09050	MARY CATHERINE 33-7-3 1	PR
294237	WELL	PR	06/03/2008	GW	067-09475	MARY CATHERINE 33-7-3 3B	PR

General Comment:[Site inspection with photos at the end of this inspection report.](#)

Location				
Lease Road:				
Type	Access			
comment:	Gravel access road through locked gate.			
Corrective Action	L			Date:
Overall Good: <input type="checkbox"/>				
Signs/Marker:				
Type	WELLHEAD			
Comment:	Sign posted at entrance to location and at pumpjacks.			
Corrective Action:				Date:
Emergency Contact Number:				
Comment:	Contact information posted.			
Corrective Action:				Date: _____
Good Housekeeping:				
Type	WEEDS			
Comment:	Weeds around separator and meter house need to be controlled.			
Corrective Action:	Comply with Rule 603.f.			Date: 06/16/2019
Type	UNUSED EQUIPMENT			
Comment:	Unused wellhead valve sitting on pumpjack needs to be removed.			
Corrective Action:	Comply with Rule 603.f.			Date: 06/16/2019
Overall Good: <input type="checkbox"/>				
Spills:				
Type	Area	Volume		
In Containment: No				
Comment:				
<input type="checkbox"/> Multiple Spills and Releases?				
Fencing/:				
Type	WELLHEAD			
Comment:	T-post and hogwire around wellhead and pumpjack.			
Corrective Action:				Date:
Equipment:				
Type: Bird Protectors	# 2			corrective date
Comment:	On separator stacks.			
Corrective Action:				Date:
Type: Gas Meter Run	# 2			
Comment:				
Corrective Action:				Date:
Type: Pump Jack	# 1			
Comment:	33-7-3 #B gearbox is leaking from seal and is staining soil and gravel. Properly treat and dispose of oily waste.			

Corrective Action:	Comply with Rule 1002.f.(2)	Date:	06/16/2019
Type: Bradenhead	# 2		
Comment:	PVC bradenhead access.		
Corrective Action:		Date:	
Type: Ancillary equipment	# 2		
Comment:	Wellhead has localized spotting of stained gravel and oily waste. Dispose of oily waste and gravel/soil.		
Corrective Action:	Comply with Rule 907.e. and Rule 1002.f.(2)	Date:	06/16/2019
Type: Pump Jack	# 1		
Comment:	33-7-3 #1 Pumpjack engine exhaust is blowing oily waste on the fuel gas knockout pot and pumpjack skid and surrounding area. Properly treat or dispose of oily waste.		
Corrective Action:	Comply with Rule 907.e. and Rule 1002.f.(2)	Date:	06/16/2019
Type: Flow Line	# 9		
Comment:	2-2" flowlines from wellhead to separator. 2-2" flowlines from separator dump valves to produced water gathering system. 2-3" flowlines from separators to meter houses. 2-4" slowlines from meter houses to offsite doglegs. 1-1" flowline from separator to pump jack fuel gas.		
Corrective Action:		Date:	
Type: Horizontal Heated Separator	# 2		
Comment:			
Corrective Action:		Date:	

Venting:

Yes/No	NO		
Comment:			
Corrective Action:		Date:	

Flaring:

Type		
Comment:		
Corrective Action:		Date:

Inspected FacilitiesFacility ID: 277814 Type: WELL API Number: 067-09050 Status: PR Insp. Status: PR**Producing Well**Comment: Producing.

Corrective Action:

Date:

Facility ID: 294237 Type: WELL API Number: 067-09475 Status: PR Insp. Status: PR**Producing Well**Comment: Producing.

Corrective Action:

Date:

Reclamation - Storm Water - Pit**Storm Water:**

Loc Erosion BMPs	BMP Maintenance	Lease Road Erosion BMPs	Lease BMP Maintenance	Chemical BMPs	Chemical BMP Maintenance	Comment
Gravel	Pass	Gravel	Pass			
				Material Handling And Spill Prevention	Fail	No spill prevention for engine oil day tanks.
Compaction	Pass	Compaction	Pass			

Comment: [No spill prevention on engine oil day tanks. Install containment to comply with Best Management Practices.](#)

Corrective Action: [Comply with Rule 1002.f.\(2\)B.](#)

Date: 06/16/2019

Pits: ☒ NO SURFACE INDICATION OF PIT

Attached Documents

You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
402046703	INSPECTION SUBMITTED	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4825272
687904790	MARY CATHERINE 33-7-3 3B Inspection photos.	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4825264