



**Location**

Overall Good:

<b>Signs/Marker:</b>			
Type	BATTERY		
Comment:	Does not contain emergency contact number. See attached photo.		
Corrective Action:		Date:	
Type	TANK LABELS/PLACARDS		
Comment:	Adequate		
Corrective Action:		Date:	
Type	WELLHEAD		
Comment:	Does not contain emergency contact number. See attached photo.		
Corrective Action:		Date:	

Emergency Contact Number:

Comment:

Corrective Action:

Date: \_\_\_\_\_

<b>Good Housekeeping:</b>			
Type	OTHER		
Comment:	Stained soil behind middle crude oil tank. See attached photo.		
Corrective Action:	Properly treat or dispose of oily waste in accordance with 907.e.	Date:	06/23/2019
Type	TRASH		
Comment:	trash/unused equipment at the head of pump jack. See attached photo.		
Corrective Action:	Comply with Rule 603.f.	Date:	06/01/2019
Type	DEBRIS		
Comment:	Door to pumpjack motor is taken off. See attached photo.		
Corrective Action:	Comply with Rule 603.f.	Date:	06/01/2019

Overall Good:

<b>Spills:</b>			
Type	Area	Volume	

In Containment: No

Comment:

Multiple Spills and Releases?

<b>Equipment:</b>			corrective date
Type: Flare	# 1		
Comment:			
Corrective Action:		Date:	
Type: Vertical Heater Treater	# 1		
Comment:			
Corrective Action:		Date:	
Type: Pump Jack	# 1		

Comment:			
Corrective Action:			Date:
Type: Emission Control Device	# 1		
Comment:			
Corrective Action:			Date:
Type: Bird Protectors	# 2		
Comment:			
Corrective Action:			Date:

**Tanks and Berms:**

Contents	#	Capacity	Type	Tank ID	SE GPS
PRODUCED WATER	1	400 BBLs	STEEL AST		
Comment:					
Corrective Action:					Date:

Paint

Condition	Adequate	
Other (Content)		
Other (Capacity)		
Other (Type)		

Berms

Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance
Comment:	Shares containment with crude oil tanks.			
Corrective Action:				Date:

Contents	#	Capacity	Type	Tank ID	SE GPS
CRUDE OIL	2	400 BBLs	STEEL AST		40.653800,-104.842300
Comment:					
Corrective Action:					Date:

Paint

Condition	Adequate	
Other (Content)		
Other (Capacity)		
Other (Type)		

Berms

Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance
Earth	Adequate	Walls Sufficient	Base Sufficient	Adequate
Comment:				
Corrective Action:				Date:

**Venting:**

Yes/No	NO		
--------	----	--	--

Comment:			
Corrective Action:		Date:	

**Flaring:**

Type			
Comment:			
Corrective Action:		Date:	

**Inspected Facilities**

Facility ID: 425151 Type: WELL API Number: 123-34284 Status: PR Insp. Status: SI

**Idle Well**

Purpose:  Shut In  Temporarily Abandoned Reminder: \_\_\_\_\_

Comment:

Corrective Action:  Date: \_\_\_\_\_

Reclamation - Storm Water - Pit						
<b>Storm Water:</b>						
Loc Erosion BMPs	BMP Maintenance	Lease Road Erosion BMPs	Lease BMP Maintenance	Chemical BMPs	Chemical BMP Maintenance	Comment
Gravel		Gravel				
Comment: <input style="width:90%;" type="text"/> Corrective Action: <input style="width:90%;" type="text"/>						Date: _____
<b>Pits:</b> <input type="checkbox"/> NO SURFACE INDICATION OF PIT						

COGCC Comments		
Comment	User	Date
<p>COGCC Inspection Report Summary                      On Wednesday, May 22, 2019 at approximately 12:59, I, Inspector Brittani Santistevan, conducted an on-site inspection at LINDSTORM 24-8-67 1H (Edge Energy), at location #: 425165 in WELD COUNTY Colorado.                      While there, I observed a shut in location.                      During this inspection the following possible compliance issues were observed:</p> <ol style="list-style-type: none"> <li>1. Battery sign does not contain emergency contact numbers. INSTALL SIGN TO COMPLY WITH RULE 210.B. (Corrective Action Date: June 22, 2019) See attached photo #4.</li> <li>2. Appears to be stained soil behind middle crude oil tank. PROPERLY TREAT OR DISPOSE OF OILY WASTE IN ACCORDANCE WITH 907.E. (Corrective Action Date: June 22, 2019) See attached photo #5.</li> <li>3. Trash/unused equipment at the head of pumpjack. COMPLY WITH RULE 603.F. (Corrective Action Date: June 1, 2019) See attached photo #6.</li> <li>4. Door to pumpjack motor is off. (debris) COMPLY WITH RULE 603.F. (Corrective Action Date: June 1, 2019) See attached photo #7.</li> </ol> <p>A follow up on this site inspection needs to be conducted to ensure the compliance issues have been corrected to comply with COGCC rules.                      This is a summary of inspection report.</p> <p>Continuing Education Inspection.</p>	santistb	05/22/2019

**Attached Documents**

You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
679600777	Photos	<a href="http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4830318">http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4830318</a>