

Inspection Photos

API: 05-071-09613

Operator: Evergreen NATURAL RESOURCES

Inspection Date: 5/22/2019



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

API: 05-071-09613 | Date: 5/22/2019

Inspection Photos



Photo 1. Facing east toward the location.



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

API: 05-071-09613 | Date: 5/22/2019

Inspection Photos



Photo 2. Facing toward the cut slope which appears to have recently been seeded and mulched. There is some rilling occurring,



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

API: 05-071-09613 | Date: 5/22/2019

Inspection Photos



Photo 3. Outlet protection is installed at the culvert.



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

API: 05-071-09613 | Date: 5/22/2019

Inspection Photos



Photo 4. There is vegetation establishment along the fill slope.



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

API: 05-071-09613 | Date: 5/22/2019

Inspection Photos



Photo 5. There is vegetation establishment along the cut slope.



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

API: 05-071-09613 | Date: 5/22/2019

Inspection Photos



Photo 6. The sediment trap at the east side of the location needs to be cleaned out.



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

API: 05-071-09613 | Date: 5/22/2019