

Inspection Photos

API: 05-071-06636

Operator: Evergreen NATURAL RESOURCES

Inspection Date: 5/22/2019



COLORADO

**Oil & Gas Conservation
Commission**

Department of Natural Resources

API: 05-071-06636 | Date: 5/22/2019

Inspection Photos



Photo 1. The erosion gully along the access road has been repaired and stabilized with rock rip/rap at Lat/Long:37.08649,-104.75026.



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

API: 05-071-06636 | Date: 5/22/2019

Inspection Photos



Photo 2. Three culverts have been installed at the access road at Lat/Long:37.08649,-104.75026.



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

API: 05-071-06636 | Date: 5/22/2019

Inspection Photos



Photo 3. Facing toward the culvert outlet and gully repair.



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

API: 05-071-06636 | Date: 5/22/2019

Inspection Photos



Photo 4. A new culvert was installed at Lat/Long:37.09338,-104.74751.



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

API: 05-071-06636 | Date: 5/22/2019