

Inspection Photos

API: 05-071-06598

Operator: Evergreen NATURAL RESOURCES

Inspection Date: 5/22/2019



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

API: 05-071-06598 | Date: 5/22/2019

Inspection Photos



Photo 1. There is erosion issues at this outlet culvert at Lat/Long:37.09868,-104.74486. No outlet protection.



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

API: 05-071-06598 | Date: 5/22/2019

Inspection Photos



Photo 2. View of erosion around the culvert.



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

API: 05-071-06598 | Date: 5/22/2019

Inspection Photos



Photo 3. There is erosion channel along the access road at Lat/Long: 37.09935, - 104.74298.



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

API: 05-071-06598 | Date: 5/22/2019

Inspection Photos



Photo 4. Facing toward the location.



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

API: 05-071-06598 | Date: 5/22/2019

Inspection Photos



Photo 5. Vegetation is established in the interim area.



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

API: 05-071-06598 | Date: 5/22/2019