

Inspection Photos

API: 05-071-06678

Operator: Evergreen NATURAL RESOURCES

Inspection Date: 5/22/2019



COLORADO

**Oil & Gas Conservation
Commission**

Department of Natural Resources

API: 05-071-06678 | Date: 5/22/2019

Inspection Photos



Photo 1. Facing south toward the location. The fill and cut slopes have been seeded and hydromulched.



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

API: 05-071-06678 | Date: 5/22/2019

Inspection Photos



Photo 2. Sign is updated.



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

API: 05-071-06678 | Date: 5/22/2019

Inspection Photos



Photo 3. The cut slope has been stabilized with hydro mulch and rock rip/rap.



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

API: 05-071-06678 | Date: 5/22/2019

Inspection Photos



Photo 4. The fill slope has been hydromulched and seeded.



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

API: 05-071-06678 | Date: 5/22/2019

Inspection Photos



Photo 5. Gravel has been placed on pad surface. Berm is adequate around tank.



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

API: 05-071-06678 | Date: 5/22/2019