

**FORM  
INSP**Rev  
X/15**State of Colorado  
Oil and Gas Conservation Commission**1120 Lincoln Street, Suite 801, Denver, Colorado 80203  
Phone: (303) 894-2100 Fax: (303) 894-2109

Inspection Date:

05/15/2019

Submitted Date:

05/23/2019

Document Number:

689401722

**FIELD INSPECTION FORM**Loc ID 322496 Inspector Name: Heil, John On-Site Inspection ☐ 2A Doc Num: \_\_\_\_\_**Operator Information:**

OGCC Operator Number: 10112

Name of Operator: FOUNDATION ENERGY MANAGEMENT LLC

Address: 5057 KELLER SPRINGS RD STE 650

City: ADDISON State: TX Zip: 75001

**Status Summary:**

- ☒ THIS IS A FOLLOW UP INSPECTION
- ☒ FOLLOW UP INSPECTION REQUIRED
- ☐ NO FOLLOW UP INSPECTION REQUIRED

**Findings:**

5 Number of Comments

4 Number of Corrective Actions

- ☒ Corrective Action Response Requested

**ANY CORRECTIVE ACTION(S) FROM  
PREVIOUS INSPECTIONS THAT HAVE NOT  
BEEN ADDRESSED ARE STILL APPLICABLE****Contact Information:**

Contact Name	Phone	Email	Comment
Fischer, Alex		alex.fischer@state.co.us	
Arauzo, Steven		steven.arauza@state.co.us	
Beard, Alyssa		regulatory@foundationenergy.com	

**Inspected Facilities:**

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
119465	PIT	AC			-	Federal #3-10-84 119465	EI
210635	WELL	PR	09/01/2018	GW	045-06391	FEDERAL 3-10-84	EI

**General Comment:**

On May 15, 2019, COGCC Environmental Staff (John Heil and Steven Arauzo) conducted an environmental field inspection of FOUNDATION ENERGY MANAGEMENT LLC (Foundation, operator# 10112) Location ID 322496 to examine pit ID 119465. Weather was sunny and temperatures about 65 degrees Fahrenheit.

The purpose of the inspection was to follow up on Remediation Project# 13164, to close pit ID# 119465 (Doc# 401962554).

**Location**Overall Good: ☐**Signs/Marker:**

Type	TANK LABELS/PLACARDS		
Comment:	NFPA placard on plastic drum (north of separator) and plastic produced water tank (south of separator) needs repair or replacement (see photos).		
Corrective Action:	Action: Install sign to comply with Rule 210.d. (30 days)	Date:	06/23/2019

**Emergency Contact Number:**

Comment:			
Corrective Action:		Date:	

**Good Housekeeping:**

Type	WEEDS		
Comment:	Site wide vegetation (pit, well head, well pad and near horizontal heated separator, see photos)		
Corrective Action:	Comply with Rule 603.f . (10 days)	Date:	06/02/2019

Overall Good: ☐**Spills:**

Type	Area	Volume		
------	------	--------	--	--

In Containment: No

Comment: ☐ Multiple Spills and Releases?**Fencing/:**

Type	PIT		
Comment:	No netting or fencing (where fencing or netting required by pit permit). Netting or fencing not maintained.		
Corrective Action:	Pit is being closed under approved F-27 (Doc# 401962554) with a date of commencement of Remediation of 6/3/2019. Inspector believes that the fence was removed for remediation activities. CA date set for completion of remediation, 10/7/2019 (Doc# 401962554).		Date: 10/07/2019

**Equipment:**

Type: Horizontal Heated Separator	#		corrective date
Comment:	Securely fasten all valves, pipes, and fittings to ensure good mechanical condition, inspect at regular intervals and maintain in good mechanical condition per Rule 605.d (see photos).		
Corrective Action:	30 days unless leak is found. Immediate call to operator if leak is found and 24 hours to fix the leak or isolate leak. (30 days)		Date: 06/23/2019

**Venting:**

Yes/No			
Comment:			
Corrective Action:			Date:

**Flaring:**

Type		
------	--	--

Comment:			
Corrective Action:		Date:	

**Inspected Facilities**Facility ID: 119465 Type: PIT API Number: - Status: AC Insp. Status: EIFacility ID: 210635 Type: WELL API Number: 045-06391 Status: PR Insp. Status: EI**Attached Documents**You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
689401735	20190519 photos	<a href="http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4830436">http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4830436</a>