

**FORM  
INSP**

Rev  
X/15

**State of Colorado  
Oil and Gas Conservation Commission**

1120 Lincoln Street, Suite 801, Denver, Colorado 80203  
Phone: (303) 894-2100 Fax: (303) 894-2109



Inspection Date:

05/15/2019

Submitted Date:

05/23/2019

Document Number:

689401729

**FIELD INSPECTION FORM**

Loc ID 322413 Inspector Name: Heil, John On-Site Inspection  2A Doc Num: \_\_\_\_\_

**Status Summary:**

- THIS IS A FOLLOW UP INSPECTION
- FOLLOW UP INSPECTION REQUIRED
- NO FOLLOW UP INSPECTION REQUIRED

**Operator Information:**

OGCC Operator Number: 10112  
Name of Operator: FOUNDATION ENERGY MANAGEMENT LLC  
Address: 5057 KELLER SPRINGS RD STE 650  
City: ADDISON State: TX Zip: 75001

**Findings:**

- 4 Number of Comments
- 3 Number of Corrective Actions
- Corrective Action Response Requested

**ANY CORRECTIVE ACTION(S) FROM PREVIOUS INSPECTIONS THAT HAVE NOT BEEN ADDRESSED ARE STILL APPLICABLE**

**Inspected Facilities:**

| Facility ID | Type | Status | Status Date | Well Class | API Num   | Facility Name        | Insp Status |
|-------------|------|--------|-------------|------------|-----------|----------------------|-------------|
| 119476      | PIT  | AC     |             |            | -         | Federal #23-4 119476 | EI          |
| 210442      | WELL | PR     | 04/01/2015  | GW         | 045-06198 | FEDERAL 23-4         | EI          |

**General Comment:**

On May 15, 2019, COGCC Environmental Staff (John Heil and Steven Arauza) conducted an environmental field inspection of FOUNDATION ENERGY MANAGEMENT LLC (Foundation, operator# 10112) Location ID 322413 to examine pit ID 119476. Weather was sunny and temperatures about 65 degrees Fahrenheit.

The purpose of the inspection was to follow up on Remediation Project# 13414, to close pit ID# 119476 (Doc# 401962566).

There is a partly buried 95 bbl produced water tank on location (south of pit ID 119476) that contains hydrocarbons (see photos). Operator has until 6/23/2019 to submit a complete eForm 15 to the COGCC (Doc# 401962566).

**Location**

Overall Good:

**Signs/Marker:**

|                    |   |       |            |
|--------------------|---|-------|------------|
| Type               | TANK LABELS/PLACARDS  |       |            |
| Comment:           | NFPA placard on plastic drums (north of separator, east of well head) needs repair or replacement (see photos). |       |            |
| Corrective Action: | Install sign to comply with Rule 210.d. (30 days)   | Date: | 06/20/2019 |

**Emergency Contact Number:**

|                    |                      |  |                            |
|--------------------|----------------------|--|----------------------------|
| Comment:           | <input type="text"/> |  |                            |
| Corrective Action: | <input type="text"/> |  | Date: <input type="text"/> |

**Good Housekeeping:**

|                    |  |       |            |
|--------------------|--|-------|------------|
| Type               | WEEDS  |       |            |
| Comment:           | Site wide vegetation (pit, well head, well pad and around horizontal heated separator, see photos) |       |            |
| Corrective Action: | Comply with Rule 603.f . (10 days)   | Date: | 06/02/2019 |

Overall Good:

**Spills:**

| Type | Area | Volume |  |  |
|------|------|--------|--|--|
|      |      |        |  |  |

In Containment: No

Comment:

Multiple Spills and Releases?

**Fencing/:**

|                    |   |  |                  |
|--------------------|---|--|------------------|
| Type               | PIT   |  |                  |
| Comment:           | No netting or fencing (where fencing or netting required by pit permit). Netting or fencing not maintained.   |  |                  |
| Corrective Action: | Pit is being closed under approved F-27 (Doc# 401962566) with a date of commencement of Remediation of 6/3/2019. Inspector believes that the fence was removed for remediation activities. CA date set for completion of remediation, 10/7/2019 (Doc# 401962566). |  | Date: 10/07/2019 |

**Venting:**

|                    |                      |       |  |
|--------------------|----------------------|-------|--|
| Yes/No             |                      |       |  |
| Comment:           | <input type="text"/> |       |  |
| Corrective Action: |                      | Date: |  |

**Flaring:**

|                    |                      |       |  |
|--------------------|----------------------|-------|--|
| Type               |                      |       |  |
| Comment:           | <input type="text"/> |       |  |
| Corrective Action: |                      | Date: |  |

**Inspected Facilities**

Facility ID: 119476 Type: PIT API Number: - Status: AC Insp. Status: EI

Facility ID: 210442 Type: WELL API Number: 045-06198 Status: PR Insp. Status: EI

**Attached Documents**

You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

| Document Num | Description     | URL   |
|--------------|-----------------|---|
| 689401730    | 20190515 photos | <a href="http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4830438">http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4830438</a> |