

**FORM  
INSP**

Rev  
X/15

**State of Colorado  
Oil and Gas Conservation Commission**

1120 Lincoln Street, Suite 801, Denver, Colorado 80203  
Phone: (303) 894-2100 Fax: (303) 894-2109



Inspection Date:

05/15/2019

Submitted Date:

05/23/2019

Document Number:

689401733

**FIELD INSPECTION FORM**

Loc ID 322412 Inspector Name: Heil, John On-Site Inspection  2A Doc Num: \_\_\_\_\_

**Status Summary:**

- THIS IS A FOLLOW UP INSPECTION
- FOLLOW UP INSPECTION REQUIRED
- NO FOLLOW UP INSPECTION REQUIRED

**Operator Information:**

OGCC Operator Number: 10112  
Name of Operator: FOUNDATION ENERGY MANAGEMENT LLC  
Address: 5057 KELLER SPRINGS RD STE 650  
City: ADDISON State: TX Zip: 75001

**Findings:**

- 4 Number of Comments
- 3 Number of Corrective Actions
- Corrective Action Response Requested

**ANY CORRECTIVE ACTION(S) FROM PREVIOUS INSPECTIONS THAT HAVE NOT BEEN ADDRESSED ARE STILL APPLICABLE**

**Contact Information:**

Contact Name	Phone	Email	Comment
Arauzo, Steven		steven.arauza@state.co.us	
Beard, Alyssa		regulatory@foundationenergy.com	
Fischer, Alex		alex.fischer@state.co.us	
Pesicka, Conor		conor.pesicka@state.co.us	

**Inspected Facilities:**

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
119480	PIT	AC			-	Federal #31-16 119480	EI
210441	WELL	SI	01/01/2019	GW	045-06197	FEDERAL 31-16	EI

**General Comment:**

On May 15, 2019, COGCC Environmental Staff (John Heil and Steven Arauzo) conducted an environmental field inspection of FOUNDATION ENERGY MANAGEMENT LLC (Foundation, operator# 10112) Location ID 322412 to examine pit ID 119480. Weather was sunny and temperatures about 65 degrees Fahrenheit.

The purpose of the inspection was to follow up on Remediation Project# 13410, to close pit ID# 119480 (Doc# 401962561).

Inspectors observed an area (2x3 feet) of oil stained soil beneath the valve of the produced water tank located on the north east side of the pit (see photos).

**Location**

Overall Good:

Emergency Contact Number:

Comment:

Corrective Action:

Date: \_\_\_\_\_

**Good Housekeeping:**

Type

WEEDS

Comment: Site wide vegetation (pit, well head, well pad and vertical separator, see photos)

Corrective Action: Comply with Rule 603.f . (10 days)

Date: 05/22/2019

Overall Good:

**Spills:**

Type

Area

Volume

Condensate

Tank

<= 1 bbl

Comment: Small localized areas of oil/condensate staining (south west side of produced water tank).

Corrective Action: Properly treat or dispose of oily waste in accordance with 907.e. 30-days to remove stained soil.

Date: 06/23/2019

In Containment: No

Comment:

Multiple Spills and Releases?

**Fencing/:**

Type

Comment: No netting or fencing (where fencing or netting required by pit permit). Netting or fencing not maintained.

Corrective Action: Pit is being closed under approved F-27 (Doc# 401962561) with a date of commencement of Remediation of 6/3/2019. Inspector believes that the fence was removed for remediation activities. CA date set for completion of remediation, 10/7/2019 (Doc# 401962561).

Date: 10/07/2019

**Venting:**

Yes/No

Comment:

Corrective Action:

Date:

**Flaring:**

Type

Comment:

Corrective Action:

Date:

**Inspected Facilities**

Facility ID: 119480 Type: PIT API Number: - Status: AC Insp. Status: EI

Facility ID: 210441 Type: WELL API Number: 045-06197 Status: SI Insp. Status: EI

**Attached Documents**

You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
689401734	20190515 photos	<a href="http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4830439">http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4830439</a>