

**FORM
INSP**Rev
X/15**State of Colorado
Oil and Gas Conservation Commission**1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109

Inspection Date:

05/23/2019

Submitted Date:

05/23/2019

Document Number:

679600811**FIELD INSPECTION FORM**
 Loc ID 333316 Inspector Name: Santistevan, Brittani On-Site Inspection ☐ 2A Doc Num: _____
Operator Information:OGCC Operator Number: 8840Name of Operator: BLUE CHIP OIL INCAddress: 155 E BOARDWALK DR STE 400City: FORT COLLINS State: CO Zip: 80525**Status Summary:**☐ THIS IS A FOLLOW UP INSPECTION☒ FOLLOW UP INSPECTION REQUIRED☐ NO FOLLOW UP INSPECTION REQUIRED**Findings:**14 Number of Comments4 Number of Corrective Actions☒ Corrective Action Response Requested**ANY CORRECTIVE ACTION(S) FROM
PREVIOUS INSPECTIONS THAT HAVE NOT
BEEN ADDRESSED ARE STILL APPLICABLE****Contact Information:**

Contact Name	Phone	Email	Comment
Kraich, Adam		adam.kraich@state.co.us	
,		bluechipoil@msn.com	

Inspected Facilities:

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
299114	WELL	PR	02/01/2019	GW	123-29265	KW 3	PR
299115	WELL	PR	02/01/2019	OW	123-29266	KW 2	PR
299118	WELL	PR	02/01/2019	GW	123-29268	KW 5	PR
299119	WELL	PR	02/01/2019	OW	123-29269	KW 1	PR

General Comment:

LocationOverall Good: ☒

Signs/Marker:			
Type	WELLHEAD		
Comment:	Adequate (x4)		
Corrective Action:		Date:	
Type	BATTERY		
Comment:	Adequate		
Corrective Action:		Date:	
Type	TANK LABELS/PLACARDS		
Comment:	Adequate		
Corrective Action:		Date:	

Emergency Contact Number:

Comment:

Corrective Action:

Date: _____

Good Housekeeping:

Type	UNUSED EQUIPMENT		
Comment:	Unused equipment in gas meter house and right side of middle separator. See attached photos.		
Corrective Action:	Comply with Rule 603.f.	Date:	06/23/2019
Type	UNUSED EQUIPMENT		
Comment:	(2) Unused horizontal separators. See attached photos		
Corrective Action:	Comply with Rule 603.f.	Date:	08/23/2019
Type	TRASH		
Comment:	Trash in gas meter house. See attached photo		
Corrective Action:	Comply with Rule 603.f.	Date:	06/02/2019
Type	OTHER		
Comment:	Stained soil at east separator. See attached photo.		
Corrective Action:	Securely fasten all valves, pipes, and fittings to ensure good mechanical condition, inspect at regular intervals and maintain in good mechanical condition per Rule 605.d.	Date:	06/23/2019

Overall Good: ☐

Spills:			
Type	Area	Volume	

In Containment: No

Comment:

☐ Multiple Spills and Releases?

Fencing/:			
Type			
Comment:			
Corrective Action:		Date:	

Equipment:			corrective date
Type: Gas Meter Run	# 1		
Comment:			
Corrective Action:			Date:
Type: Emission Control Device	# 2		
Comment:			
Corrective Action:			Date:
Type: Plunger Lift	# 4		
Comment:			
Corrective Action:			Date:
Type: Bird Protectors	# 6		
Comment:			
Corrective Action:			Date:
Type: Horizontal Heated Separator	# 4		
Comment:			
Corrective Action:			Date:

Tanks and Berms:

Contents	#	Capacity	Type	Tank ID	SE GPS
PRODUCED WATER	1	300 BBLS	STEEL AST		,
Comment:					
Corrective Action:					Date:

Paint

Condition	Adequate	
Other (Content)		
Other (Capacity)		
Other (Type)		

Berms

Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance	
Comment:	Shares containment with crude oil tanks.				
Corrective Action:				Date:	
Contents	#	Capacity	Type	Tank ID	SE GPS
PRODUCED WATER	3	OTHER	PBV CONCRETE		,
Comment:					
Corrective Action:					
Date:					

Paint

Condition	Adequate	
Other (Content)		
Other (Capacity)	60 BBLS	
Other (Type)		

Berms

Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance	
Comment:	Shares containment with crude oil tanks.				
Corrective Action:					Date:
Contents	#	Capacity	Type	Tank ID	SE GPS
CRUDE OIL	4	300 BBLs	STEEL AST		40.508300,-104.834300
Comment:					
Corrective Action:					Date:

Paint

Condition	Adequate	
Other (Content)		
Other (Capacity)		
Other (Type)		

Berms

Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance	
Earth	Adequate	Walls Sufficient	Base Sufficient	Adequate	
Comment:					
Corrective Action:					Date:

Venting:

Yes/No	NO		
Comment:			
Corrective Action:			Date:

Flaring:

Type			
Comment:			
Corrective Action:			Date:

Inspected Facilities									
Facility ID:	299114	Type:	WELL	API Number:	123-29265	Status:	PR	Insp. Status:	PR
Producing Well									
Comment:	PR								
Corrective Action:						Date:			
Facility ID:	299115	Type:	WELL	API Number:	123-29266	Status:	PR	Insp. Status:	PR
Producing Well									
Comment:	PR								
Corrective Action:						Date:			
Facility ID:	299118	Type:	WELL	API Number:	123-29268	Status:	PR	Insp. Status:	PR
Producing Well									
Comment:	PR								
Corrective Action:						Date:			
Facility ID:	299119	Type:	WELL	API Number:	123-29269	Status:	PR	Insp. Status:	PR
Producing Well									
Comment:	PR								
Corrective Action:						Date:			

Reclamation - Storm Water - Pit**Storm Water:**

Loc Erosion BMPs	BMP Maintenance	Lease Road Erosion BMPs	Lease BMP Maintenance	Chemical BMPs	Chemical BMP Maintenance	Comment
Gravel		Gravel				

Comment: Corrective Action: Date: **Pits:** ☐ NO SURFACE INDICATION OF PIT**COGCC Comments**

Comment	User	Date
<p>COGCC Inspection Report Summary On Thursday, May 23, 2019 at approximately 15:30, I, Inspector Brittani Santistevan, conducted an on-site inspection at KW 1, 5, 3, 2 (Blue Chip Oil), at location #: 333316 in WELD COUNTY Colorado. While there, I observed producing wells and location. During this inspection the following possible compliance issues were observed:</p> <ol style="list-style-type: none"> 1. Stained soil left side of east separator. SECURELY FASTEN ALL VALVES, PIPES, AND FITTINGS TO ENSURE GOOD MECHANICAL CONDITION, INSPECT AT REGULAR INTERVALS AND MAINTAIN IN GOOD MECHANICAL CONDITIONS PER RULE 605.D. (Corrective Action Date: June 23, 2019) See attached photo #2. 2. Trash inside gas meter house. COMPLY WITH RULE 603.F. (corrective Action Date: June 2, 2019) See attached photo #3. 3. Unused used equipment inside gas meter house, right side of middle separator, and two disconnected separators. COMPLY WITH RULE 603.F. (Corrective Action Date: August 23, 2019) See attached photos #4-7. <p>A follow up on this site inspection needs to be conducted to ensure the compliance issues have been corrected to comply with COGCC rules. This is a summary of inspection report.</p> <p>Continuing Education Inspection.</p>	santistb	05/23/2019

Attached DocumentsYou can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
679600812	Wellhead photo	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4831176
679600813	Wellhead Photo	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4831177
679600814	Wellhead Photo	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4831178
679600815	Wellhead Photo	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4831179
679600816	Location Photos	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4831180