

Inspection Photos
Location Name: KEIDO 14-6
API #: 05-071-08150
INSP. #:695100651



PHOTO 1: ORIGINAL WELLHEAD

PHOTO 2: TR WELLHEAD

Inspection Photos
Location Name: KEIDO 14-6
API #: 05-071-08150
INSP. #:695100651



Colorado Oil & Gas Conservation Commission
37.19413, -104.82537, 2175.0m, 270°
2019/05/20 10:33:15



Colorado Oil & Gas Conservation Commission
37.19407, -104.82581, 2176.0m, 175°
2019/05/20 10:34:59

PHOTO 3: LOCATION SIGNS POSTED ON METER HOUSE

PHOTO 4: NO NFPA SIGNS POSTED ON PRODUCED WATER TANK. **Install sign to comply with Rule 210.d. CA DATE 7/20/19**

Inspection Photos

Location Name: KEIDO 14-6 & TR WELL

API #: 05-071-08150 & 08629

INSP. #:695100651



PHOTO 5: NO BERMS AROUND PRODUCED WATER TANK. Repair or install berms or other secondary containment devices per Rule 605. CA DATE 6/30/18

PHOTO 4: NO NFPA SIGNS POSTED ON PRODUCED WATER TANK. Install sign to comply with Rule 210.d. CA DATE 7/20/19