

Inspection Photos
Location Name: ELVIRIA 24-12
API #: 05-071-09528
INSP. #:695100655



PHOTO 1: WELLHEAD/ IMPACTED SOIL. increase frequency of maintenance and self inspection schedule of equipment to prevent impacting surface materials and mixing of wastes with precipitation"
CA DATE 6/20/19

PHOTO 2: WELL SIGN NOT DEPICTING CURRENT OPERATOR. COMPLY WITH RULE 210. CA DATE 7/20/19