

**FORM
INSP**Rev
X/15**State of Colorado
Oil and Gas Conservation Commission**1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109

Inspection Date:

05/20/2019

Submitted Date:

05/20/2019

Document Number:

695100651**FIELD INSPECTION FORM**Loc ID 333464 Inspector Name: Beardslee, Tom On-Site Inspection ☐ 2A Doc Num: _____**Operator Information:**OGCC Operator Number: 10705Name of Operator: EVERGREEN NATURAL RESOURCES LLCAddress: 1801 BROADWAY SUITE 350City: DENVER State: CO Zip: 80202**Status Summary:**

- ☒
- THIS IS A FOLLOW UP INSPECTION
-
- ☒
- FOLLOW UP INSPECTION REQUIRED
-
- ☐
- NO FOLLOW UP INSPECTION REQUIRED

Findings:7 Number of Comments3 Number of Corrective Actions

- ☒
- Corrective Action Response Requested

**ANY CORRECTIVE ACTION(S) FROM
PREVIOUS INSPECTIONS THAT HAVE NOT
BEEN ADDRESSED ARE STILL APPLICABLE****Contact Information:**

Contact Name	Phone	Email	Comment
Distribution, Evergreen		cogcc.evergreen@enrllc.com	All Inspections

Inspected Facilities:

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
273233	WELL	PR	02/10/2005	GW	071-08150	KEIKO 14-6	PR
281717	WELL	PR	02/02/2008	GW	071-08629	KEIKO 14-6 TR	PR

General Comment:

LocationOverall Good: ☒

Signs/Marker:			
Type	TANK LABELS/PLACARDS		
Comment:	PHOTO 4: NO NFPA SIGNS POSTED ON PRODUCED WATER TANK.		
Corrective Action:	Install sign to comply with Rule 210.d.	Date:	07/20/2019
Type	OTHER		
Comment:	The Qtr-Qtr of the Keiko 14-6 is SESW and the Qtr-Qtr of the Keiko 14-6 TR is SWSW on the lease signs. The Lot to the West is not a true 40 acres. I believe that the correct Qtr-Qtr for both wells is SESW. The footages also don't reflect this. The AS Drilled : Lat/Long on both well might reflect this.		
Corrective Action:	Pioneer needs to investigate and possibly correct the Lease sign on the Keiko 14-6 TR (05-071-8629) well to SESW. Contact (COGCC)Dennis Ahlstrand : 303-894-2100, xt 5116 of any changes. CA FROM LAST INSPECTION NOT ADDRESSED DOC #687902080	Date:	06/30/2018

Emergency Contact Number:

Comment:

Corrective Action:

Date: _____

Overall Good: ☒

Spills:				
Type	Area	Volume		

In Containment: No

Comment:

☐ Multiple Spills and Releases?

Equipment:			corrective date
Type: Bradenhead	# 2		
Comment:	IS PLUMBED TO SURFACE		
Corrective Action:		Date:	
Type: Ancillary equipment	# 2		
Comment:	TELEMETRY EQUIPMENT		
Corrective Action:		Date:	

Tanks and Berms:

Contents	#	Capacity	Type	Tank ID	SE GPS
PRODUCED WATER	1	500 BBLS	STEEL AST		,
Comment:					
Corrective Action:					Date:

Paint

Condition	Adequate
Other (Content)	
Other (Capacity)	
Other (Type)	

Berms					
Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance	
	Inadequate	Walls Insufficient	Base Insufficient	Inadequate	
Comment:	PHOTO 5: NO BERMS AROUND PRODUCED WATER TANK.				
Corrective Action:	Repair or install berms or other secondary containment devices per Rule 605. CA FROM PREVIOUS INSPECTION DOC #687902080			Date:	06/30/2018

Venting:			
Yes/No	NO		
Comment:			
Corrective Action:		Date:	

Flaring:			
Type			
Comment:			
Corrective Action:		Date:	

Inspected FacilitiesFacility ID: 273233 Type: WELL API Number: 071-08150 Status: PR Insp. Status: PR**Producing Well**

Comment:

Corrective Action:

Date:

Facility ID: 281717 Type: WELL API Number: 071-08629 Status: PR Insp. Status: PR**Producing Well**

Comment:

Corrective Action:

Date:

Reclamation - Storm Water - Pit**Storm Water:**

Loc Erosion BMPs	BMP Maintenance	Lease Road Erosion BMPs	Lease BMP Maintenance	Chemical BMPs	Chemical BMP Maintenance	Comment

Comment: Corrective Action: Date: **Pits:** ☒ NO SURFACE INDICATION OF PIT**COGCC Comments**

Comment	User	Date
THIS IS A FOLLOWUP INSPECTION TO INSPECTION DOC#687902080. CORRECTIVE ACTIONS HAVE NOT BEEN ADDRESS AND THERE IS AN ADDITIONAL CORRECTIVE ACTION AT TIME OF THIS INSPECTION THAT WAS NOT NOTED ON PREVIOUS INSPECTION (SEE TANKS LABELS/PLACARDS SECTION OF THIS INSPECTION).	beardslt	05/20/2019

Attached DocumentsYou can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
695100652	LCATION PHOTOS	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4831310