

**FORM
INSP**Rev
X/15**State of Colorado
Oil and Gas Conservation Commission**1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109

Inspection Date:

05/23/2019

Submitted Date:

05/24/2019

Document Number:

696100936**FIELD INSPECTION FORM**

Loc ID 305864 Inspector Name: Evins, Bret On-Site Inspection ☐ 2A Doc Num: _____

Operator Information:OGCC Operator Number: 100322Name of Operator: NOBLE ENERGY INCAddress: 1001 NOBLE ENERGY WAYCity: HOUSTON State: TX Zip: 77070**Status Summary:**

- ☐ THIS IS A FOLLOW UP INSPECTION
- ☐ FOLLOW UP INSPECTION REQUIRED
- ☒ NO FOLLOW UP INSPECTION REQUIRED

Findings:7 Number of Comments0 Number of Corrective Actions☐ Corrective Action Response Requested**ANY CORRECTIVE ACTION(S) FROM
PREVIOUS INSPECTIONS THAT HAVE NOT
BEEN ADDRESSED ARE STILL APPLICABLE****Contact Information:**

Contact Name	Phone	Email	Comment
,		NBL_DJBU_Inspections@nblenergy.com	All Inspections

Inspected Facilities:

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
282984	WELL	SI	09/01/2017	OW	123-23595	PEPPLER 18-44	TA

General Comment:

This is a WELL Inspection.
 Well: Temporarily Abandoned (TA).
 Battery: Abandoned & ALL equipment removed.
 Abandoned Battery SE corner GPS coordinates: 40.487727, -104.472509
 Reclamation progressing.
 Abandoned Centralized Battery formerly served 3 Location IDs (306252, 305864, 310828). (Wells: TA, TA, PA)

Location**Lease Road:**

Type	Access		
comment:	Adequate		
Corrective Action:		Date:	

Overall Good: ☐**Signs/Marker:**

Type	WELLHEAD		
Comment:			
Corrective Action:		Date:	

Emergency Contact Number:

Comment:		
Corrective Action:		Date: _____

Overall Good: ☐**Spills:**

Type	Area	Volume		
------	------	--------	--	--

In Containment: No

Comment: ☐ Multiple Spills and Releases?**Fencing/:**

Type	WELLHEAD		
Comment:	Iron panel		
Corrective Action:		Date:	

Equipment:

Type: Bradenhead	# 1		corrective date
Comment:	Appears plumbed to surface.		
Corrective Action:		Date:	
Type: Plunger Lift	# 1		
Comment:			
Corrective Action:		Date:	

Venting:

Yes/No	NO		
Comment:			
Corrective Action:		Date:	

Flaring:

Type		
Comment:		
Corrective Action:		Date:

Inspected Facilities									
Facility ID:	282984	Type:	WELL	API Number:	123-23595	Status:	SI	Insp. Status:	TA
Idle Well									
Purpose:		<input type="checkbox"/> Shut In		<input checked="" type="checkbox"/> Temporarily Abandoned		Reminder: EQUIPMENT PRESENT/DISCONNECTED			
Comment:		<div>TA. Battery has been abandoned. Locked & Tag-out. Orange Decommission tag present. COGCC records indicate last prod: 12/2015. SI/TA. MIT requirement waived per variance Doc #401474555. (NOBLE)</div>							
Corrective Action:							Date:		

Reclamation - Storm Water - Pit**Storm Water:**

Loc Erosion BMPs	BMP Maintenance	Lease Road Erosion BMPs	Lease BMP Maintenance	Chemical BMPs	Chemical BMP Maintenance	Comment
Gravel						

Comment:

Corrective Action:

Date: _____

Pits: ☐ NO SURFACE INDICATION OF PIT**COGCC Comments**

Comment	User	Date
<p>COGCC Inspection Report Summary:</p> <p>On TUE MAY 21, 2019 at approximately 15:31 hrs. I, Bret Evins, conducted an on-site inspection at: Operator Name: NOBLE ENERGY INC Location Name: PEPPLER-66N63W /18SESE Location ID: 305864 Location County: Weld County, Colorado Weather: Damp from prior rain.</p> <p>While there, I observed: 1-Well(s) Temporarily Abandoned (TA) & Abandoned Battery. Abandoned Battery SE corner GPS coordinates: 40.487727, -104.472509 Abandoned Centralized Battery formerly served 3 Location IDs (306252, 305864, 310828). (Wells: TA, TA, PA). Reclamation progressing.</p> <p>NO: Corrective Actions observed.</p> <p>This is a summary of the inspection report.</p>	evinsb	05/24/2019

Attached DocumentsYou can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
696100937	Site photos	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4832229