

**FORM  
INSP**Rev  
X/15**State of Colorado  
Oil and Gas Conservation Commission**1120 Lincoln Street, Suite 801, Denver, Colorado 80203  
Phone: (303) 894-2100 Fax: (303) 894-2109

Inspection Date:

05/23/2019

Submitted Date:

05/24/2019

Document Number:

688800528**FIELD INSPECTION FORM**Loc ID 322111 Inspector Name: Hughes, Jim On-Site Inspection ☐ 2A Doc Num: \_\_\_\_\_**Operator Information:**OGCC Operator Number: 10343Name of Operator: QEP ENERGY COMPANYAddress: 1050 17TH STREET - SUITE 800City: DENVER State: CO Zip: 80265**Status Summary:**

- ☐ THIS IS A FOLLOW UP INSPECTION
- ☐ FOLLOW UP INSPECTION REQUIRED
- ☒ NO FOLLOW UP INSPECTION REQUIRED

**Findings:**12 Number of Comments1 Number of Corrective Actions☒ Corrective Action Response Requested**ANY CORRECTIVE ACTION(S) FROM  
PREVIOUS INSPECTIONS THAT HAVE NOT  
BEEN ADDRESSED ARE STILL APPLICABLE****Contact Information:**

Contact Name	Phone	Email	Comment
Fischer, Alex		alex.fischer@state.co.us	
Heil, John		john.heil@state.co.us	
Jacobson, Julie	303-595-5919	julie.jacobson@qepres.com	

**Inspected Facilities:**

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
208988	WELL	IJ	07/23/1993	DSPW	033-06093	SPARGO 2	EI
437560	SPILL OR RELEASE	AC	06/10/2014		-	SPILL/RELEASE POINT	EI

**General Comment:**

On May 23, 2019 COGCC SW EPS Jim Hughes conducted an environmental field inspection of the QEP Energy Company Spargo #2. For the most recent field inspection report of this facility, please refer to document #680603123. This site visit was conducted to follow up on Spill/Release Point ID #437560. QEP is listed in the COGIS database as the operator of record for this location.

**Location**

<b>Lease Road:</b>			
Type	Access		
comment:			
Corrective Action	L	Date:	

Overall Good: ☒

<b>Signs/Marker:</b>			
Type	WELLHEAD		
Comment:	Sign posted near location entrance. Sticker with Seeley Oil contact information attached to it.		
Corrective Action:		Date:	
Type	TANK LABELS/PLACARDS		
Comment:	ASTs are labeled with contents, capacity and have placards.		
Corrective Action:		Date:	
Type	TANK LABELS/PLACARDS		
Comment:	Tinhorn labeled produced water does not have capacity listed.		
Corrective Action:	Install sign to comply with Rule 210.d.	Date:	07/24/2019

Emergency Contact Number:

Comment:	Posted on location sign.	
Corrective Action:		Date: _____

**Good Housekeeping:**

Type	STORAGE OF SUPL		
Comment:	Triple P Rig #6, enclosed trailer, and power swivel skid with BOP on site.		
Corrective Action:		Date:	

Overall Good: ☒

<b>Spills:</b>			
Type	Area	Volume	

In Containment: No

Comment: ☐ Multiple Spills and Releases?

<b>Equipment:</b>			corrective date
Type: Deadman # & Marked	# 4		
Comment:			
Corrective Action:		Date:	
Type: Ancillary equipment	# 1		
Comment:	Injection pump in building.		
Corrective Action:		Date:	

**Tanks and Berms:**

Contents	#	Capacity	Type	Tank ID	SE GPS
PRODUCED WATER	1	OTHER	BV STEEL		37.586251,-109.007441

Comment:	Open topped buried section of culvert pipe (tinhorn) with expanded metal lid. Labeled produced water.					Date:	
Corrective Action:						Date:	
<u>Paint</u>							
Condition							
Other (Content)							
Other (Capacity)	unkown						
Other (Type)							
<u>Berms</u>							
Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance			
Earth	Adequate	Walls Sufficent	Base Sufficent	Adequate			
Comment:						Date:	
Corrective Action:						Date:	
Contents	#	Capacity	Type	Tank ID	SE GPS		
CRUDE OIL	1	400 BBLS	STEEL AST		37.585588,-109.007474		
Comment:	Tank not in use.					Date:	
Corrective Action:						Date:	
<u>Paint</u>							
Condition	Adequate						
Other (Content)							
Other (Capacity)							
Other (Type)							
<u>Berms</u>							
Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance			
Earth	Adequate	Walls Sufficent	Base Sufficent	Adequate			
Comment:						Date:	
Corrective Action:						Date:	
Contents	#	Capacity	Type	Tank ID	SE GPS		
PRODUCED WATER	5	400 BBLS	STEEL AST		37.586336,-109.007509		
Comment:	3 400bbl. and 2 500 bbl. ASTs.					Date:	
Corrective Action:						Date:	
<u>Paint</u>							
Condition	Adequate						
Other (Content)							
Other (Capacity)							
Other (Type)							
<u>Berms</u>							
Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance			
Earth	Adequate	Walls Sufficent	Base Sufficent	Adequate			
Comment:						Date:	
Corrective Action:						Date:	



Inspected Facilities									
Facility ID:	208988	Type:	WELL	API Number:	033-06093	Status:	IJ	Insp. Status:	EI
Facility ID:	437560	Type:	SPILL OR	API Number:	-	Status:	AC	Insp. Status:	EI

**Reclamation - Storm Water - Pit****Storm Water:**

Loc Erosion BMPs	BMP Maintenance	Lease Road Erosion BMPs	Lease BMP Maintenance	Chemical BMPs	Chemical BMP Maintenance	Comment
Compaction	Pass	Compaction	Pass	Material Handling And Spill Prevention	Pass	

Comment: Secondary containment for 55 gal. drum labeled rock oil, chemical injection system labeled corrosion inhibitor, and lube oil container. Drip pot at truck load out.

Corrective Action:

Date: \_\_\_\_\_

**Pits:** ☒ NO SURFACE INDICATION OF PIT

**COGCC Comments**

Comment	User	Date
On May 23, 2019 COGCC SW EPS Jim Hughes conducted an environmental field inspection of the QEP Energy Company Spargo #2. For the most recent field inspection report of this facility, please refer to document #680603123. This site visit was conducted to follow up on Spill/Release Point ID #437560. QEP is listed in the COGIS database as the operator of record for this location. During this inspection an RW Trucking water hauler was delivering produced water reportedly from the Spargo #1-36. Triple P Rig #6 and associated equipment was being stored on location.	hughesjo	05/24/2019

**Attached Documents**

You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
688800529	Inspection Photos	<a href="http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4832358">http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4832358</a>