

**FORM  
INSP**Rev  
X/15**State of Colorado  
Oil and Gas Conservation Commission**1120 Lincoln Street, Suite 801, Denver, Colorado 80203  
Phone: (303) 894-2100 Fax: (303) 894-2109

Inspection Date:

05/23/2019

Submitted Date:

05/24/2019

Document Number:

696100938**FIELD INSPECTION FORM**
 Loc ID 310651 Inspector Name: Evins, Bret On-Site Inspection ☐ 2A Doc Num:                     
**Operator Information:**OGCC Operator Number: 10110Name of Operator: GREAT WESTERN OPERATING COMPANY LLCAddress: 1001 17TH STREET #2000City: DENVER State: CO Zip: 80202**Status Summary:**

- ☒ THIS IS A FOLLOW UP INSPECTION
- ☐ FOLLOW UP INSPECTION REQUIRED
- ☒ NO FOLLOW UP INSPECTION REQUIRED

**Findings:**16 Number of Comments0 Number of Corrective Actions☐ Corrective Action Response Requested**ANY CORRECTIVE ACTION(S) FROM  
PREVIOUS INSPECTIONS THAT HAVE NOT  
BEEN ADDRESSED ARE STILL APPLICABLE****Contact Information:**

Contact Name	Phone	Email	Comment
Pesicka, Conor		conor.pesicka@state.co.us	
,		cogccinspections@gwogco.com	<a href="#">All Inspections</a>

**Inspected Facilities:**

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
296335	WELL	SI	02/01/2019	GW	123-26749	PEPPLER 17-12	SI

**General Comment:**

This is a WELL & BATTERY inspection.  
 Well: Shut-In (SI).  
 Entire battery & equipment is shut-down.  
 Centralized Battery serves 2 Location IDs (310651, 310057). (1-well per location).  
 Follow-up to Field Inspection Report Doc #696100880 dated 05/09/2019.

Location				
<b>Lease Road:</b>				
Type	Access			
comment:	Adequate			
Corrective Action	L			Date:
Overall Good: <input type="checkbox"/>				
<b>Signs/Marker:</b>				
Type	BATTERY			
Comment:				
Corrective Action:				Date:
Type	WELLHEAD			
Comment:				
Corrective Action:				Date:
Type	TANK LABELS/PLACARDS			
Comment:	<p>Prior insp: Capacity Not Legible on condensate tanks. Refer to Rule 210.e (60 Days). Post Legible capacity on condensate tanks to comply w/ Rule 210.e. Corrective Action date: 07/09/2019.</p> <p>This insp: * Capacity NOW Legible on condensate tanks. See photos #3, 4.</p>			
Corrective Action:				Date:
Emergency Contact Number:				
Comment:	<p>Prior insp: Emergency number NOT posted at wellsite. Refer to Rule 210.b (30 Days). Post Emergency number at wellsite. Comply w/ Rule 210.b. Corrective Action date: 06/10/2019.</p> <p>This insp: * Emergency number NOW posted at wellsite. See photos #1, 2.</p>			
Corrective Action:				Date:
<b>Good Housekeeping:</b>				
Type	OTHER			
Comment:	<p>Prior insp: Stained soil below loadouts on East &amp; West condensate tanks. Oily waste. Refer to Rule 907.e (30 Days). Remove or remediate stained soil below tank loadouts to comply w/ Rule 907.e. Corrective Action date: 06/10/2019.</p> <p>This insp: * Stained soil below loadouts on East &amp; West condensate tanks NOW appears mitigated. See photos #5-8.</p>			
Corrective Action:				Date:
Overall Good: <input type="checkbox"/>				
<b>Spills:</b>				
Type	Area	Volume		

In Containment: No

Comment: ☐ Multiple Spills and Releases?**Fencing/:**

Type WELLHEAD

Comment: [Iron panel.](#)

Corrective Action:

Date:

**Equipment:**

corrective date

Type: Horizontal Heated Separator

# 1

Comment:

Corrective Action:

Date:

Type: Emission Control Device

# 1

Comment: [Controls crude oil tank VOCs.](#)  
[Pilots: OFF | Shut-down.](#)

Corrective Action:

Date:

Type: Ancillary equipment

# 1

Comment: [ECD scrubber.](#)

Corrective Action:

Date:

Type: Bird Protectors

# 2

Comment:

Corrective Action:

Date:

Type: Gas Meter Run

# 1

Comment:

Corrective Action:

Date:

Type: Bradenhead

# 1

Comment: [Appears plumbed to surface.](#)

Corrective Action:

Date:

Type: Plunger Lift

# 1

Comment:

Corrective Action:

Date:

**Tanks and Berms:**

Contents	#	Capacity	Type	Tank ID	SE GPS
			CENTRALIZED BATTERY		,
Comment: <a href="#">Centralized Battery serves 2 Location IDs (310651, 310057).</a>					
Corrective Action:					Date:

**Paint**

Condition

Other (Content)

Other (Capacity)

Other (Type)

Berms						
Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance		
Comment:						
Corrective Action:				Date:		
Contents	#	Capacity	Type	Tank ID	SE GPS	
PRODUCED WATER	1	100 BBLs	PBV FIBERGLASS		,	
Comment:						
Corrective Action:				Date:		
Paint						
Condition						
Other (Content)						
Other (Capacity)						
Other (Type)						
Berms						
Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance		
Earth	Adequate	Walls Sufficient	Base Sufficient	Adequate		
Comment: <a href="#">Shares berms w/ condensate tanks.</a>						
Corrective Action:				Date:		
Contents	#	Capacity	Type	Tank ID	SE GPS	
CONDENSATE	2	300 BBLs	STEEL AST		40.489739,	
Comment: <a href="#">Equalizer line connects condensate tanks.</a>						
Corrective Action:				Date:		
Paint						
Condition	Adequate					
Other (Content)						
Other (Capacity)						
Other (Type)						
Berms						
Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance		
Earth	Adequate	Walls Sufficient	Base Sufficient	Adequate		
Comment: <a href="#">Shares berms w/ produced H2O tank.</a>						
Corrective Action:				Date:		
Venting:						
Yes/No	NO					
Comment:						
Corrective Action:						Date:
Flaring:						
Type						
Comment:						

Corrective Action:		Date:	
--------------------	--	-------	--

Inspected Facilities									
Facility ID:	296335	Type:	WELL	API Number:	123-26749	Status:	SI	Insp. Status:	SI
Idle Well									
Purpose:		<input checked="" type="checkbox"/> Shut In		<input type="checkbox"/> Temporarily Abandoned		Reminder: PRODUCTION RECORDS			
Comment:		<div>SI. Observed production valves shut. COGCC records indicate last prod: 01/2019.</div>							
Corrective Action:		<div></div>						Date:	

**Reclamation - Storm Water - Pit****Storm Water:**

Loc Erosion BMPs	BMP Maintenance	Lease Road Erosion BMPs	Lease BMP Maintenance	Chemical BMPs	Chemical BMP Maintenance	Comment
Gravel		Gravel				

Comment: Corrective Action: Date: **Pits:** ☐ NO SURFACE INDICATION OF PIT**COGCC Comments**

Comment	User	Date
<p><b>COGCC Inspection Report Summary:</b></p> <p>On THU 05/23/2019 at approximately 16:11 hrs. I, Bret Evins, conducted an on-site inspection at:  Operator Name: GREAT WESTERN OPERATING COMPANY LLC  Location Name: PEPPLER-66N63W /17SWNW  Location ID: 310651  Location County: Weld County, Colorado  Weather: Damp conditions from prior rain.</p> <p>While there, I observed: Well(s) - 1: SI.  Entire battery &amp; equipment is shut-down.  Centralized Battery serves 2 Location IDs (310651, 310057).  Follow-up to Field Inspection Report Doc #696100880 dated 05/09/2019.  3 of 3: Corrective Actions appear addressed.  1.) Emergency number NOT posted at wellsite. Refer to Rule 210.b (30 Days).  Post Emergency number at wellsite. Comply w/ Rule 210.b.  Corrective Action date: 06/10/2019.  * Emergency number NOW posted at wellsite.  See photos #1, 2.  2.) Capacity Not Legible on condensate tanks. Refer to Rule 210.e (60 Days).  Post Legible capacity on condensate tanks to comply w/ Rule 210.e.  Corrective Action date: 07/09/2019.  * Capacity NOW Legible on condensate tanks.  See photos #3, 4.  3.) Stained soil below loadouts on East &amp; West condensate tanks.  Oily waste. Refer to Rule 907.e (30 Days).  Remove or remediate stained soil below tank loadouts to comply w/ Rule 907.e.  Corrective Action date: 06/10/2019.  * Stained soil below loadouts on East &amp; West condensate tanks NOW appears mitigated.  See photos #5-8.</p> <p>NO: Corrective Actions observed on this inspection.</p> <p>This is a summary of the inspection report.</p>	evinsb	05/24/2019

**Attached Documents**You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
696100939	Site photos	<a href="http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4832355">http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4832355</a>