

State of Colorado
Oil and Gas Conservation Commission

1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109



Document Number:

402055904

Date Received:

05/27/2019

FIR RESOLUTION FORM

Overall Status: CAC

CA Summary:

1 of 5 CAs from the FIR responded to on this Form

1 CA Completed
0 Factual Review Request

OPERATOR INFORMATION

OGCC Operator Number: 83130
Name of Operator: STRACHAN EXPLORATION INC
Address: 383 INVERNESS PKWY, STE 360
City: ENGLEWOOD State: CO Zip: 80112

Contact Name and Telephone:
Name:
Phone: () Fax: ()
Email:

Additional Operator Contact:

Contact Name	Phone	Email
Stephen M Strachan	303-790-9115	sms@strachanexploration.com

COGCC INSPECTION SUMMARY:

FIR Document Number: 689900681
Inspection Date: 05/15/2019 FIR Submit Date: 05/16/2019 FIR Status:

Inspected Operator Information:

Company Name: STRACHAN EXPLORATION INC Company Number: 83130
Address: 383 INVERNESS PKWY, STE 360
City: ENGLEWOOD State: CO Zip: 80112

LOCATION - Location ID: 384631

Location Name: FRAZEE-619S50W Number: 9N2 County:
Qtrqr: SW Sec: 9 Twp: 19S Range: 50W Meridian: 6
Latitude: 38.427729 Longitude: -103.013502

FACILITY - API Number: 05-061-00 Facility ID: 150131

Facility Name: SALT LAKE UNIT Number:
Qtrqr: SW Sec: 9 Twp: 19S Range: 50W Meridian: 6
Latitude: 38.427729 Longitude: -103.013502

CORRECTIVE ACTIONS:

2 CA# 125201

Corrective Action: Securely fasten all valves, pipes, and fittings to ensure good mechanical condition, inspect at regular intervals and maintain in good mechanical condition per Rule 605.d.

Date: 05/17/2019

Response: CA COMPLETED Date of Completion: 05/17/2019

Operator Comment: Pumpers were notified that a leak at water tank had occurred at the Salt lake Water Disposal Site. Pumpers inspected immediately. Water had been hauled earlier from this water tank due to the water disposal well for the field being shut-in due to a suspected hole in the tubing discovered when an pre-MIT test was conducted (Helfrich #1, water injection well for Salt Lake Field, is currently being worked on to pull tubing). Water truck had not completely shut valve, so there was a minor water drip. All valves were inspected by pumpers and secured closed. Plug installed in valve.

COGCC Decision: _____

COGCC
Representative: _____

OPERATOR COMMENT AND SUBMITTAL

Comment: Pumpers responded immediately to call from COGCC regarding a water leak at the Salt Lake Field Water Disposal Site. Water had been recently hauled off this particular water tank as the water disposal well, Helfrich #1, was shut-in due to a suspected tubing leak discovered during a pre-MIT test. Valve had not been completely closed after pulling water, resulting in a minor water drip. Valve was secured. All valves inspected and secured. Plug installed in valve.

I hereby certify that the statements made in this form are, to the best of my knowledge, true, correct, and complete.

Print Name: Stephen M Strachan

Signed: _____

Title: President

Date: 5/27/2019 1:51:23 PM

ATTACHMENT LIST

View Attachments in Imaged Documents on COGCC website (<http://ogccweblink.state.co.us/>) - Search by Document Number.

<u>Document Number</u>	<u>Description</u>
------------------------	--------------------

--	--

Total Attach: 0 Files