

MARALEX RESOURCES, INC.– 53255
API # 05-067-09621 ARTFGANCE 33-7-14 #2A
API # 05-067-09623 ARTFGANCE 33-7-14 #3C
Inspection Date : 05/14/2019



**Overview of location from SW corner of pad
looking NE**



Meter housings with signs

MARALEX RESOURCES, INC.– 53255
API # 05-067-09621 ARTFGANCE 33-7-14 #2A
API # 05-067-09623 ARTFGANCE 33-7-14 #3C
Inspection Date : 05/14/2019



Separators with chemical injector in secondary containment



Unused tanks and walkway sections

MARALEX RESOURCES, INC.– 53255
API # 05-067-09621 ARTFGANCE 33-7-14 #2A
API # 05-067-09623 ARTFGANCE 33-7-14 #3C
Inspection Date : 05/14/2019



API # 05-067-09623 ARTFGANCE 33-7-14 #3C
API # 05-067-09621 ARTFGANCE 33-7-14 #2A
Pumpjacks and guyline anchor with marker.



API # 05-067-09623 ARTFGANCE 33-7-14 #3C
Wellhead with stained soil

MARALEX RESOURCES, INC.– 53255
API # 05-067-09621 ARTFGANCE 33-7-14 #2A
API # 05-067-09623 ARTFGANCE 33-7-14 #3C
Inspection Date : 05/14/2019



API # 05-067-09623 ARTFGANCE 33-7-14 #3C
Motor oil container with no secondary containment



API # 05-067-09623 ARTFGANCE 33-7-14 #3C
Wellhead sign

MARALEX RESOURCES, INC.– 53255
API # 05-067-09621 ARTFGANCE 33-7-14 #2A
API # 05-067-09623 ARTFGANCE 33-7-14 #3C
Inspection Date : 05/14/2019



API # 05-067-09621 ARTFGANCE 33-7-14 #2A
Wellhead sign



API # 05-067-09621 ARTFGANCE 33-7-14 #2A
Wellhead with stained soil

MARALEX RESOURCES, INC.– 53255
API # 05-067-09621 ARTFGANCE 33-7-14 #2A
API # 05-067-09623 ARTFGANCE 33-7-14 #3C
Inspection Date : 05/14/2019



API # 05-067-09621 ARTFGANCE 33-7-14 #2A
Motor oil container with no secondary containment



API # 05-067-09621 ARTFGANCE 33-7-14 #2A
Washed out 10" diameter hole ~20' NE of wellhead.
Noted changing fluid levels and intermittent bubbles.