

MARALEX RESOURCES, INC.– 53255

Location ID # 311950

Inspection Date : 05/14/2019



Overview of location from NE corner of pad
looking SW



Meter housings with signs

MARALEX RESOURCES, INC.– 53255

Location ID # 311950

Inspection Date : 05/14/2019



API# 05-067-09474 Mollie Corynne 33-7-2 #3B

Wellhead with pump jack



API# 05-067-09474 Mollie Corynne 33-7-2 #3B

Stained soil around wellhead requires remediation.

MARALEX RESOURCES, INC.– 53255

Location ID # 311950

Inspection Date : 05/14/2019



API# 05-067-08039 Mollie Corynne 33-7-2 #1

Wellhead with pump jack.

Unused tubing and stair section needs removal.



API# 05-067-08039 Mollie Corynne 33-7-2 #1

Stained soil around wellhead requires remediation.

MARALEX RESOURCES, INC.– 53255

Location ID # 311950

Inspection Date : 05/14/2019



Unused tubing on SE corner of pad needs removal.



Pump jack belt cover on SE edge of pad need removal.

MARALEX RESOURCES, INC.– 53255

Location ID # 311950

Inspection Date : 05/14/2019



**E side separator. Possible leaks detected.
See FLIR photos for leak inspection.**



W side separator.

MARALEX RESOURCES, INC.– 53255

Location ID # 311950

Inspection Date : 05/14/2019



W side separator. Control valve with corrosion and staining.



Trash and junk along NE side of location.