

**FORM  
INSP**Rev  
X/15**State of Colorado  
Oil and Gas Conservation Commission**1120 Lincoln Street, Suite 801, Denver, Colorado 80203  
Phone: (303) 894-2100 Fax: (303) 894-2109

Inspection Date:

05/14/2019

Submitted Date:

05/27/2019

Document Number:

693800277**FIELD INSPECTION FORM**Loc ID 325477 Inspector Name: BROWNING, CHUCK On-Site Inspection ☐ 2A Doc Num: \_\_\_\_\_**Operator Information:**OGCC Operator Number: 53255Name of Operator: MARALEX RESOURCES INCAddress: P O BOX 338City: IGNACIO State: CO Zip: 81137**Status Summary:**☐ THIS IS A FOLLOW UP INSPECTION☒ FOLLOW UP INSPECTION REQUIRED☐ NO FOLLOW UP INSPECTION REQUIRED**Findings:**12 Number of Comments2 Number of Corrective Actions☒ Corrective Action Response Requested**ANY CORRECTIVE ACTION(S) FROM  
PREVIOUS INSPECTIONS THAT HAVE NOT  
BEEN ADDRESSED ARE STILL APPLICABLE****Contact Information:**

| Contact Name     | Phone        | Email                       | Comment                         |
|------------------|--------------|-----------------------------|---------------------------------|
| Ried, Jordan     | 970-563-400  | maralextechjr@gmail.com     | <a href="#">All Inspections</a> |
| Ferrin, Jeremy   |              | jeremy.ferrin@state.co.us   |                                 |
| Labowskie, Steve |              | steve.labowskie@state.co.us |                                 |
| Browning, Chuck  | 970-433-4139 | chuck.browning@state.co.us  | <a href="#">Field Inspector</a> |

**Inspected Facilities:**

| Facility ID | Type | Status | Status Date | Well Class | API Num   | Facility Name           | Insp Status |
|-------------|------|--------|-------------|------------|-----------|-------------------------|-------------|
| 214856      | WELL | PR     | 02/01/2019  | GW         | 067-06460 | MAGDALEN CLARE 33-7-2 2 | PR          |

**General Comment:**

COGCC staff performed a routine field inspection on 5/14/2019.  
Housekeeping and equipment issues were found requiring corrective action.  
See inspection text and photos for details.

**Location**

|                    |              |       |  |
|--------------------|--------------|-------|--|
| <b>Lease Road:</b> |              |       |  |
| Type               | Main         |       |  |
| comment:           |              |       |  |
| Corrective Action  | L            | Date: |  |
| Type               | Access       |       |  |
| comment:           | Private road |       |  |
| Corrective Action  | L            | Date: |  |

Overall Good: ☒

|                      |                                      |       |  |
|----------------------|--------------------------------------|-------|--|
| <b>Signs/Marker:</b> |                                      |       |  |
| Type                 | WELLHEAD                             |       |  |
| Comment:             | Signs at Wellhead and Meter Housing. |       |  |
| Corrective Action:   |                                      | Date: |  |
| Type                 | TANK LABELS/PLACARDS                 |       |  |
| Comment:             | Sign on blowdown tank fence          |       |  |
| Corrective Action:   |                                      | Date: |  |

|                           |  |             |
|---------------------------|--|-------------|
| Emergency Contact Number: |  |             |
| Comment:                  |  |             |
| Corrective Action:        |  | Date: _____ |

|                           |  |       |            |
|---------------------------|--|-------|------------|
| <b>Good Housekeeping:</b> |  |       |            |
| Type                      | UNUSED EQUIPMENT   |       |            |
| Comment:                  | Disconnected and unused flowline on W side of separator. |       |            |
| Corrective Action:        | Remove unused equipment per rule 603.f.                  | Date: | 06/28/2019 |

Overall Good: ☒

|                |      |        |  |
|----------------|------|--------|--|
| <b>Spills:</b> |      |        |  |
| Type           | Area | Volume |  |

In Containment: No

Comment: ☐ Multiple Spills and Releases?

|                      |   |       |                 |
|----------------------|---|-------|-----------------|
| <b>Equipment:</b>    |   |       | corrective date |
| Type: Flow Line      | # 2   |       |                 |
| Comment:             | Unused flowline on E. side of separator. Unused riser E. of equipment |       |                 |
| Corrective Action:   |   | Date: |                 |
| Type: Gas Meter Run  | # 1   |       |                 |
| Comment:             |   |       |                 |
| Corrective Action:   |   | Date: |                 |
| Type: Gathering Line | # 1   |       |                 |
| Comment:             |   |       |                 |
| Corrective Action:   |   | Date: |                 |

|                                   |   |                  |
|-----------------------------------|---|------------------|
| Type: Bradenhead                  | # 1   |                  |
| Comment:                          |   |                  |
| Corrective Action:                |   | Date:            |
| Type: Other                       | # 2   |                  |
| Comment:                          | Domestic taps. Existing prior to May 1 2018.<br>No CA until 10/31/2019<br>Submit an eForm 44 Flowline Report per Rule 1101.b. |                  |
| Corrective Action:                |   | Date:            |
| Type: Horizontal Heated Separator | # 1   |                  |
| Comment:                          | Active bird nest inside separator housing. No screen on separator stack.  |                  |
| Corrective Action:                | Install wildlife screen per Rule 605.b.(7).   | Date: 06/28/2019 |
| Type: Deadman # & Marked          | # 4   |                  |
| Comment:                          |   |                  |
| Corrective Action:                |   | Date:            |

**Tanks and Berms:**

| Contents           | #  | Capacity | Type           | Tank ID | SE GPS                |
|--------------------|--|----------|----------------|---------|-----------------------|
| OTHER              | 1  | <50 BBLS | PBV FIBERGLASS |         | 37.135858,-107.582528 |
| Comment:           | Blowdown in tank with fence and netting. |          |                |         |                       |
| Corrective Action: |  |          |                |         | Date:                 |

**Paint**

|                  |          |
|------------------|----------|
| Condition        | Adequate |
| Other (Content)  |          |
| Other (Capacity) |          |
| Other (Type)     |          |

**Berms**

| Type               | Capacity | Permeability (Wall) | Permeability (Base) | Maintenance |
|--------------------|----------|---------------------|---------------------|-------------|
| Earth              | Adequate | Walls Sufficient    | Base Sufficient     | Adequate    |
| Comment:           |          |                     |                     |             |
| Corrective Action: |          |                     |                     | Date:       |

**Venting:**

|                    |       |
|--------------------|-------|
| Yes/No             | NO    |
| Comment:           |       |
| Corrective Action: | Date: |

**Flaring:**

|                    |       |
|--------------------|-------|
| Type               |       |
| Comment:           |       |
| Corrective Action: | Date: |

| Inspected Facilities |           |       |      |             |           |         |    |               |    |
|----------------------|-----------|-------|------|-------------|-----------|---------|----|---------------|----|
| Facility ID:         | 214856    | Type: | WELL | API Number: | 067-06460 | Status: | PR | Insp. Status: | PR |
| Producing Well       |           |       |      |             |           |         |    |               |    |
| Comment:             | Producing |       |      |             |           |         |    |               |    |
| Corrective Action:   |           |       |      | Date:       |           |         |    |               |    |

**Reclamation - Storm Water - Pit****Storm Water:**

| Loc Erosion BMPs | BMP Maintenance | Lease Road Erosion BMPs | Lease BMP Maintenance | Chemical BMPs | Chemical BMP Maintenance | Comment |
|------------------|-----------------|-------------------------|-----------------------|---------------|--------------------------|---------|
| Compaction       | Pass            | Compaction              | Pass                  |               |                          |         |

Comment: Corrective Action: Date: **Pits:** ☐ NO SURFACE INDICATION OF PIT**Attached Documents**You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

| Document Num | Description                 | URL   |
|--------------|-----------------------------|---|
| 693800278    | Inspection photos 5/14/2019 | <a href="http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4832858">http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4832858</a> |