

**FORM
INSP**Rev
X/15**State of Colorado
Oil and Gas Conservation Commission**1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109

Inspection Date:

05/10/2019

Submitted Date:

05/28/2019

Document Number:

696600058**FIELD INSPECTION FORM**Loc ID 312550 Inspector Name: Wentzel, Dougo On-Site Inspection ☐ 2A Doc Num: _____**Operator Information:**OGCC Operator Number: 53255Name of Operator: MARALEX RESOURCES INCAddress: P O BOX 338City: IGNACIO State: CO Zip: 81137**Status Summary:**

- ☒ THIS IS A FOLLOW UP INSPECTION
- ☒ FOLLOW UP INSPECTION REQUIRED
- ☐ NO FOLLOW UP INSPECTION REQUIRED

Findings:14 Number of Comments3 Number of Corrective Actions☒ Corrective Action Response Requested**ANY CORRECTIVE ACTION(S) FROM
PREVIOUS INSPECTIONS THAT HAVE NOT
BEEN ADDRESSED ARE STILL APPLICABLE****Contact Information:**

Contact Name	Phone	Email	Comment
Graves, Jim		mrinc20@qwestoffice.net	
Kellerby, Shaun		shaun.kellerby@state.co.us	All Inspections
Ried, Jordan	970-563-400	maralextechjr@gmail.com	All Inspections
Hartman, Robert	970-244-3041	bhartman@blm.gov	All Inspections
, DNR		dnr_cogccengineering@state.co.us	All Engineering

Inspected Facilities:

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
221894	WELL	SI	07/01/1982	GW	077-08496	USA 1-5MR	TA

General Comment:

This is a follow up inspection to FIR Doc#689401076 and 689401622 dated 9/18/18. Any corrective actions not addressed from previous inspections are still applicable.

Location			
Lease Road:			
Type	Access		
comment:	BLM access May 1		
Corrective Action	L		Date:
Overall Good: <input checked="" type="checkbox"/>			
Signs/Marker:			
Type	WELLHEAD		
Comment:			
Corrective Action:			Date:
Emergency Contact Number:			
Comment:	911/ 970-858-8550		
Corrective Action:			Date: _____
Good Housekeeping:			
Type	OTHER		
Comment:	Fire pit on location approximately 60 feet from wellhead		
Corrective Action:	Comply with Rule 603.f .		Date: 06/28/2019
Type	OTHER		
Comment:	Vegetation around wellhead. Corrective action has not been completed.		
Corrective Action:	Comply with Rule 603.f .		Date: 01/18/2019
Overall Good: <input type="checkbox"/>			
Spills:			
Type	Area	Volume	
In Containment: No			
Comment: _____			
<input type="checkbox"/> Multiple Spills and Releases?			
Fencing/:			
Type	PIT		
Comment:	Fence around dry unused pit on location at this time.		
Corrective Action:			Date:
Equipment:			
			corrective date
Type: Deadman # & Marked	# 2		
Comment:			
Corrective Action:			Date:
Type: Bradenhead	# 0		
Comment:			
Corrective Action:			Date:
Venting:			
Yes/No	NO		

Comment:			
Corrective Action:		Date:	
Flaring:			
Type			
Comment:			
Corrective Action:		Date:	

Type			
Comment:			
Corrective Action:		Date:	

Type			
Comment:			
Corrective Action:		Date:	

Inspected FacilitiesFacility ID: 221894 Type: WELL API Number: 077-08496 Status: SI Insp. Status: TA**Idle Well**Purpose: ☐ Shut In ☒ Temporarily Abandoned Reminder: _____

Comment: Production records show well has been shut in since January 1999. No production equipment on site. No MIT on file. Form 4 Doc#401175092 approved 1/5/17 for TA status. COA States: "Approval of this Sundry fulfills condition number 11 of Maralex ACO 1V-609. Per Rule 319 b.(1) Maralex will need to submit annual sundry notice for continued temporary abandonment stating the method by which the well is closed to the atmosphere and plans for future operation." No current Form 4 on file.

Corrective Action: A Sundry Notice, Form 4, shall be submitted annually stating the method the well is closed to the atmosphere and plans for future operation.

Date: 03/27/2018

Reclamation - Storm Water - Pit**Storm Water:**

Loc Erosion BMPs	BMP Maintenance	Lease Road Erosion BMPs	Lease BMP Maintenance	Chemical BMPs	Chemical BMP Maintenance	Comment
Berms	Pass					
Compaction	Pass					
		Compaction	Pass			
Gravel	Pass					
		Gravel	Pass			

Comment: At time of inspection stormwater Erosion appears to be controlled.

Corrective Action:

Date: _____

Pits: ☐ NO SURFACE INDICATION OF PIT

Type: Blowdown

Lined: NO

Pit ID:

Lat:

Long:

Reference Point: _____

Other: _____

Length: _____

Width: _____

Lining:

Liner Type:

Liner Condition:

Comment:

Corrective Action

Date:

Fencing:

Fencing Type: Wildlife

Fencing Condition:

Comment: Pit was dry at time of inspection with vegetation established in and around it.

Corrective Action

Date:

Netting:

Netting Type:

Netting Condition:

Comment:

Corrective Action

Date:

Anchor Trench Present:

Oil Accumulation: NO

2+ feet Freeboard:

Comment:

Corrective Action

Date:

COGCC Comments

Comment	User	Date
<p>On Friday) (Date 05/10/2019) at approximately (1149), I, Inspector Dougo Wentzel, conducted a (Routine FIU General Field Inspection) at (Maralex) (USA 1-5), at (API #077-08496) in (Mesa, county) Colorado. While there, I observed a (Production location operation only) During this inspection the following possible compliance issues were observed: Vegetation growth around wellhead. A fire pit approximately 60 feet from wellhead. No current Form 4 on file.</p> <p>No MIT on file., No current Form 4 on file. (Refer to Corrective Action Matrix for comments, corrective actions, and corrective action date). Refer to photograph of observed compliance issue. A follow up on this site inspection will be conducted to ensure the compliance issues have been corrected to comply with COGCC rules. (if correction actions are identified) This is a summary of inspection report.</p>	wentzeld	05/10/2019

Attached Documents

You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
696600059	Inspection 696600058 photos	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4832864