

Inspection Photos

API: 05-071-07956

Operator: PRESCO INC

Inspection Date: 5/24/2019



COLORADO

**Oil & Gas Conservation
Commission**

Department of Natural Resources

API: 05-071-07956 | Date: 5/24/2019

Inspection Photos



Photo 1. There is erosion issues along the main road to the location.
Lat/Long:37.02250,-104.48266. The road was widened during operations.



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

API: 05-071-07956 | Date: 5/24/2019

Inspection Photos



Photo 2. There is a deep channel that developed along the side of road. Arrow points to 4.5 ft. shovel to show depth.



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

API: 05-071-07956 | Date: 5/24/2019

Inspection Photos



Photo 3. There is erosion issues along the road traveling toward the location.



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

API: 05-071-07956 | Date: 5/24/2019

Inspection Photos



Photo 4. There are numerous noxious weeds along the road. (Scotch thistle)



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

API: 05-071-07956 | Date: 5/24/2019

Inspection Photos



Photo 5. There is an erosion channel near the location along the road..



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

API: 05-071-07956 | Date: 5/24/2019

Inspection Photos



Photo 6. Facing east toward the location.



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

API: 05-071-07956 | Date: 5/24/2019

Inspection Photos



Photo 7. A shallow pit remains per approved variance request.



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

API: 05-071-07956 | Date: 5/24/2019

Inspection Photos



Photo 8. East side of the location facing west.



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

API: 05-071-07956 | Date: 5/24/2019