

Construction and Stormwater Inspection

May 24, 2019

Operator: KERR MCGEE OIL & GAS ONSHORE LP #47120

Location ID: 460362

Inspection Document #: 697500160

Weld County, CO

NESE Section 12 T1N R68W

Chris Binschus
Reclamation Specialist, COGCC



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

Inspection Photos
Location Name: TULA /9-12HZ PAD
Location ID: 460362



Photo 1. Photo taken from the southeastern location, facing North. Ditch and berm BMP has been installed around the entire perimeter of the location in conjunction with other BMPs (i.e., sediment traps). Operator plans to install a larger permanent sediment trap prior to drilling operations.



Photo 2. Photo taken from the northeastern location, facing West. See comments under Photo 1. Photo also illustrates one of two topsoil stockpiles.

Inspection Photos
Location Name: TULA /9-12HZ PAD
Location ID: 460362



Photo 3. Photo taken from the northeastern location, facing South. See comments under Photo 1.



Photo 4. Photo taken from the southern location, facing East. See comments under Photo 1.

Inspection Photos
Location Name: TULA /9-12HZ PAD
Location ID: 460362



Photo 5. Photo taken from the southeastern sediment trap, facing East. See comments under Photo 1.



Photo 6. Photo taken from the southeastern location, facing North. See comments under Photo 1.

Inspection Photos
Location Name: TULA /9-12HZ PAD
Location ID: 460362



Photo 7. Photo taken from the second topsoil stockpile, facing Northwest.
Topsoil salvage operations were in process during the time of this inspection.

Inspection Photos
Location Name: TULA /9-12HZ PAD
Location ID: 460362



Photo 8. Photo taken from the entrance of location, facing East. Street sweeper was cleaning entrance to location.