

**FORM
INSP**

Rev
X/15

**State of Colorado
Oil and Gas Conservation Commission**

1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109



Inspection Date:

05/28/2019

Submitted Date:

05/28/2019

Document Number:

685101020

FIELD INSPECTION FORM

Loc ID 433035 Inspector Name: MEDINA, JUSTIN On-Site Inspection 2A Doc Num: _____

Status Summary:

- THIS IS A FOLLOW UP INSPECTION
- FOLLOW UP INSPECTION REQUIRED
- NO FOLLOW UP INSPECTION REQUIRED

Operator Information:

OGCC Operator Number: 10633
Name of Operator: CRESTONE PEAK RESOURCES OPERATING LLC
Address: 1801 CALIFORNIA STREET #2500
City: DENVER State: CO Zip: 80202

Findings:

- 8 Number of Comments
- 2 Number of Corrective Actions
- Corrective Action Response Requested

ANY CORRECTIVE ACTION(S) FROM PREVIOUS INSPECTIONS THAT HAVE NOT BEEN ADDRESSED ARE STILL APPLICABLE

Contact Information:

Contact Name	Phone	Email	Comment
,		dnr_cogccengineering@state.co.us	
Canfield, Chris		chris.canfield@state.co.us	
Gomez, Jason		jason.gomez@state.co.us	
,		Cogcc.inspections@crestonepr.com	ALL INSPECTIONS

Inspected Facilities:

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
433031	WELL	PR	04/01/2017	OW	123-37428	Maier 4B-28H	PR
433032	WELL	PR	04/01/2017	OW	123-37429	Maier 4A-28H	PR

General Comment:

Location

Overall Good:

Emergency Contact Number: _____

Comment: _____

Corrective Action: _____ Date: _____

Good Housekeeping:

Type	WEEDS		
Comment:	Weeds around wellhead see pic 3&4		
Corrective Action:	Comply with Rule 603.f .	Date:	06/07/2019

Overall Good:

Spills:

Type	Area	Volume	
Other	WELLHEAD		
Comment:	Unknown substance in water around wellheads, water appears to be stained green see pic 1,2,3,4 &5 as comparison of other standing water on location.		
Corrective Action:	Non E&P Waste not properly stored, handled, transported, treated, or disposed per Rule 907A. Contact COGCC EPS staff.	Date:	05/30/2019

In Containment: No

Comment: _____

Multiple Spills and Releases?

Fencing/:

Type	LOCATION		
Comment:	6' chain link with barb wire around all equipment		
Corrective Action:		Date:	

Equipment:

Type			corrective date
Type: VRU	# 1		
Comment:			
Corrective Action:		Date:	
Type: Horizontal Heated Separator	# 2		
Comment:			
Corrective Action:		Date:	
Type: Emission Control Device	# 2		
Comment:			
Corrective Action:		Date:	
Type: Pig Station	# 1		
Comment:			
Corrective Action:		Date:	
Type: Plunger Lift	# 2		
Comment:			
Corrective Action:		Date:	

Type: Gas Meter Run	# 2		
Comment:			
Corrective Action:			Date:
Type: Bird Protectors	# 4		
Comment:			
Corrective Action:			Date:
Type: Ancillary equipment	# 3		
Comment:	Automation		
Corrective Action:			Date:
Type: VRT	# 2		
Comment:			
Corrective Action:			Date:
Type: Bradenhead	# 2		
Comment:			
Corrective Action:			Date:

Tanks and Berms:

Contents	#	Capacity	Type	Tank ID	SE GPS
PRODUCED WATER	2	200 BBLs	PBV FIBERGLASS		
Comment:					
Corrective Action:					Date:

Paint

Condition	Adequate	
Other (Content)		
Other (Capacity)		
Other (Type)		

Berms

Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance
Comment:	Shares containment with oil tanks			
Corrective Action:				Date:

Contents	#	Capacity	Type	Tank ID	SE GPS
CONDENSATE	12	500 BBLs	STEEL AST		40.105170,-104.777660
Comment:					
Corrective Action:					Date:

Paint

Condition	Adequate	
Other (Content)		
Other (Capacity)		
Other (Type)		

Berms

Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance	
Metal	Adequate	Walls Sufficent	Base Sufficent	Adequate	
Comment:					
Corrective Action:				Date:	

Venting:

Yes/No	NO		
Comment:			
Corrective Action:			Date:

Flaring:

Type		
Comment:		
Corrective Action:		Date:

Inspected Facilities

Facility ID: 433031 Type: WELL API Number: 123-37428 Status: PR Insp. Status: PR

Facility ID: 433032 Type: WELL API Number: 123-37429 Status: PR Insp. Status: PR

Producing Well

Comment: PR

Corrective Action:

Date:

Reclamation - Storm Water - Pit

Storm Water:

Loc Erosion BMPs	BMP Maintenance	Lease Road Erosion BMPs	Lease BMP Maintenance	Chemical BMPs	Chemical BMP Maintenance	Comment
Gravel	Pass	Gravel	Pass	Material Handling And Spill Prevention	Pass	

Comment:

Corrective Action:

Date: _____

Pits: NO SURFACE INDICATION OF PIT

COGCC Comments

Comment	User	Date
<p>COGCC Inspection Report Summary On 5/28/19 at approximately 1200 I, Inspector Justin Medina conducted an on-site inspection at Crestone Peak- API -123-37428 - Maier #4b-28H in Weld County Colorado. While there, I observed Producing well During this inspection the following possible compliance issues were observed: Weeds around wellhead see pic 3&4 Comply with Rule 603.f . 6/7/19 Unknown substance in water around wellheads, water appears to be stained green see pic 1,2,3,4 &5 as comparison of other standing water on location. Non E&P Waste not properly stored, handled, transported, treated, or disposed per Rule 907A. Contact COGCC EPS staff. 5/30/19 A follow up on this site inspection needs to be conducted to ensure the compliance issues have been corrected to comply with COGCC rules. This is a summary of inspection report. Continuing Education Inspection</p>	medinaj	05/28/2019

Attached Documents

You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
685101021	pics	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4833559