

**FORM
INSP**

Rev
X/15

**State of Colorado
Oil and Gas Conservation Commission**

1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109



Inspection Date:

05/23/2019

Submitted Date:

05/28/2019

Document Number:

689500982

FIELD INSPECTION FORM

Loc ID 321261 Inspector Name: Oakman, Kari On-Site Inspection 2A Doc Num: _____

Status Summary:

- THIS IS A FOLLOW UP INSPECTION
- FOLLOW UP INSPECTION REQUIRED
- NO FOLLOW UP INSPECTION REQUIRED

Operator Information:

OGCC Operator Number: 79905
Name of Operator: SMITH OIL PROPERTIES INC
Address: PO BOX 219
City: BYERS State: CO Zip: 80103

Findings:

- 4 Number of Comments
- 3 Number of Corrective Actions
- Corrective Action Response Requested

ANY CORRECTIVE ACTION(S) FROM PREVIOUS INSPECTIONS THAT HAVE NOT BEEN ADDRESSED ARE STILL APPLICABLE

Contact Information:

Contact Name	Phone	Email	Comment
Shelley, Vicki	303-825-7405	smithoilprop@aol.com	

Inspected Facilities:

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
114886	PIT				-	FUTHEY 1	EI
206551	WELL	PR	04/14/1996	GW	013-06046	FUTHEY 3	EI

General Comment:

COGCC Environmental Inspection to determine the status of pit facility ID 114886. Any corrective actions from previous inspections that have not been addressed are still applicable.

COGCC personnel found no surface indication of a pit present in the location. Records review and aerial photos found no evidence that there was a produced water pit on location; historic inspection reports document a concrete water vault then fiberglass tank on location. The pit status has been changed to closed, however, no associated remediation or site investigation has been conducted. Should future conditions at the site indicate contaminant concentrations in soils exceeding COGCC standards or if ground water is found to be impacted, then further investigation and/or remediation activities may be required.

Photos attached to document site condition at the time of inspection.

Location

Overall Good:

Emergency Contact Number:

Comment:

Corrective Action:

Date: _____

Good Housekeeping:

Type	WEEDS		
Comment:	Weeds present on location within tank battery berms (photos 7&8)		
Corrective Action:	Comply with Rule 603.f .	Date:	06/23/2019
Type	OTHER		
Comment:	Berm surrounding tanks is beginning to erode near loadout (photo 5)		
Corrective Action:	Repair or install berms or other secondary containment devices per Rule 906.d.(1).	Date:	06/23/2019
Type	OTHER		
Comment:	Localized stained gravel at loadout (photo 6)		
Corrective Action:	Treat or dispose of oily waste in accordance with Rule 907.e.	Date:	06/23/2019

Overall Good:

Spills:

Type	Area	Volume		

In Containment: No

Comment:

Multiple Spills and Releases?

Venting:

Yes/No			
Comment:			
Corrective Action:		Date:	

Flaring:

Type		
Comment:		
Corrective Action:		Date:

Inspected Facilities

Facility ID: 114886 Type: PIT API Number: - Status: _____ Insp. Status: EI

Facility ID: 206551 Type: WELL API Number: 013-06046 Status: PR Insp. Status: EI

Attached Documents

You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
689500983	Inspection Photos	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4833606