

**FORM
INSP**

Rev
X/15

**State of Colorado
Oil and Gas Conservation Commission**

1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109



Inspection Date:

05/23/2019

Submitted Date:

05/28/2019

Document Number:

689500980

FIELD INSPECTION FORM

Loc ID 336380 Inspector Name: Oakman, Kari On-Site Inspection 2A Doc Num: _____

Status Summary:

- THIS IS A FOLLOW UP INSPECTION
- FOLLOW UP INSPECTION REQUIRED
- NO FOLLOW UP INSPECTION REQUIRED

Operator Information:

OGCC Operator Number: 10633
Name of Operator: CRESTONE PEAK RESOURCES OPERATING LLC
Address: 1801 CALIFORNIA STREET #2500
City: DENVER State: CO Zip: 80202

Findings:

2 Number of Comments
0 Number of Corrective Actions
 Corrective Action Response Requested

ANY CORRECTIVE ACTION(S) FROM PREVIOUS INSPECTIONS THAT HAVE NOT BEEN ADDRESSED ARE STILL APPLICABLE

Contact Information:

Contact Name	Phone	Email	Comment
,		Cogcc.inspections@crestone pr.com	All Inspections

Inspected Facilities:

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
114790	PIT				-	SHIELDS 2	EI
206609	WELL	PR	05/18/1984	GW	013-06104	DONIPHAN-SHIELDS 2	EI
289602	WELL	PR	06/12/2007	GW	013-06541	DONIPHAN SHIELDS 12-11	EI
446795	TANK BATTERY	AC	07/21/2016		-	DONIPHAN-SHIELDS-61N69W 11NENW	EI

General Comment:

COGCC Environmental Inspection to determine the status of pit facility ID 114790. Any corrective actions from previous inspections that have not been addressed are still applicable.

COGCC personnel found no surface indication of a pit present in the location. Records review and aerial photos found no evidence that there was a produced water pit on location; historic inspection reports document a concrete water vault and tinhorn on location. The pit status has been changed to closed, however, no associated remediation or site investigation has been conducted. Should future conditions at the site indicate contaminant concentrations in soils exceeding COGCC standards or if ground water is found to be impacted, then further investigation and/or remediation activities may be required.

Photos attached to document site condition at the time of inspection.

Inspected Facilities

Facility ID: <u>114790</u>	Type: <u>PIT</u>	API Number: <u>-</u>	Status: <u></u>	Insp. Status: <u>EI</u>
Facility ID: <u>206609</u>	Type: <u>WELL</u>	API Number: <u>013-06104</u>	Status: <u>PR</u>	Insp. Status: <u>EI</u>
Facility ID: <u>289602</u>	Type: <u>WELL</u>	API Number: <u>013-06541</u>	Status: <u>PR</u>	Insp. Status: <u>EI</u>
Facility ID: <u>446795</u>	Type: <u>TANK</u>	API Number: <u>-</u>	Status: <u>AC</u>	Insp. Status: <u>EI</u>

Attached Documents

You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
689500981	Inspection photos	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4833603