

**FORM  
INSP**Rev  
X/15**State of Colorado  
Oil and Gas Conservation Commission**1120 Lincoln Street, Suite 801, Denver, Colorado 80203  
Phone: (303) 894-2100 Fax: (303) 894-2109

Inspection Date:

05/23/2019

Submitted Date:

05/28/2019

Document Number:

689500984**FIELD INSPECTION FORM**Loc ID 321309 Inspector Name: Oakman, Kari On-Site Inspection ☐ 2A Doc Num: \_\_\_\_\_**Operator Information:**OGCC Operator Number: 10575Name of Operator: 8 NORTH LLCAddress: 370 17TH STREET SUITE 5300City: DENVER State: CO Zip: 80202**Status Summary:**

- ☐ THIS IS A FOLLOW UP INSPECTION
- ☐ FOLLOW UP INSPECTION REQUIRED
- ☒ NO FOLLOW UP INSPECTION REQUIRED

**Findings:**2 Number of Comments0 Number of Corrective Actions☐ Corrective Action Response Requested**ANY CORRECTIVE ACTION(S) FROM  
PREVIOUS INSPECTIONS THAT HAVE NOT  
BEEN ADDRESSED ARE STILL APPLICABLE****Contact Information:**

| Contact Name | Phone | Email                                 | Comment                                   |
|--------------|-------|---------------------------------------|---|
| ,            |       | COGCCInspections@extracti<br>onog.com | All Inspections inc 8 North, 7 North, XPR |

**Inspected Facilities:**

| Facility ID | Type | Status | Status Date | Well Class | API Num   | Facility Name | Insp Status |
|-------------|------|--------|-------------|------------|-----------|---------------|-------------|
| 114873      | PIT  |        |             |            | -         | ROCKWELL 1-1  | EI          |
| 206635      | WELL | PR     | 04/12/1992  | GW         | 013-06130 | FCR 1-8       | EI          |

**General Comment:**

COGCC Environmental Inspection to determine the status of pit facility ID 114873. Any corrective actions from previous inspections that have not been addressed are still applicable.

COGCC personnel found no surface indication of a pit present in the location. Records review and aerial photos found no evidence that there was a produced water pit on location; historic inspection reports document a concrete water vault on location. The pit status has been changed to closed, however, no associated remediation or site investigation has been conducted. Should future conditions at the site indicate contaminant concentrations in soils exceeding COGCC standards or if ground water is found to be impacted, then further investigation and/or remediation activities may be required.

Photos attached to document site condition at the time of inspection.

**Inspected Facilities**Facility ID: 114873 Type: PIT API Number: - Status:  Insp. Status: EIFacility ID: 206635 Type: WELL API Number: 013-06130 Status: PR Insp. Status: EI**Attached Documents**You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

| Document Num | Description       | URL   |
|--------------|-------------------|---|
| 689500985    | Inspection photos | <a href="http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4833609">http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4833609</a> |