

**FORM  
INSP**

Rev  
X/15

**State of Colorado  
Oil and Gas Conservation Commission**

1120 Lincoln Street, Suite 801, Denver, Colorado 80203  
Phone: (303) 894-2100 Fax: (303) 894-2109



Inspection Date:

05/20/2019

Submitted Date:

05/28/2019

Document Number:

689802725

**FIELD INSPECTION FORM**

Loc ID 313030 Inspector Name: Waldron, Emily On-Site Inspection  2A Doc Num: \_\_\_\_\_

**Status Summary:**

- THIS IS A FOLLOW UP INSPECTION
- FOLLOW UP INSPECTION REQUIRED
- NO FOLLOW UP INSPECTION REQUIRED

**Operator Information:**

OGCC Operator Number: 10550  
Name of Operator: MUSTANG RESOURCES LLC  
Address: 1660 LINCOLN STREET SUITE 1450  
City: DENVER State: CO Zip: 80264

**Findings:**

- 6 Number of Comments
- 2 Number of Corrective Actions
- Corrective Action Response Requested

**ANY CORRECTIVE ACTION(S) FROM PREVIOUS INSPECTIONS THAT HAVE NOT BEEN ADDRESSED ARE STILL APPLICABLE**

**Contact Information:**

| Contact Name   | Phone        | Email                           | Comment          |
|----------------|--------------|---------------------------------|------------------|
| Couts, Brandon |              | bcoutts@mustangresourcesllc.com | Field Operations |
| Pesicka, Conor |              | conor.pesicka@state.co.us       |                  |
| Lemon, Deb     | 303-807-5112 | dlemon@mustangresourcesllc.com  |                  |

**Inspected Facilities:**

| Facility ID | Type | Status | Status Date | Well Class | API Num   | Facility Name | Insp Status |
|-------------|------|--------|-------------|------------|-----------|---------------|-------------|
| 223391      | WELL | SI     | 10/01/2018  | GW         | 081-06755 | STATE 9-36    | SI          |

**General Comment:**

COGCC Inspection 689802725 Report Summary  
On Monday 05/20/2019 at approximately 11:40, I, Inspector Emily Waldron, conducted a field inspection at Mustang Resources LLC State 9-36, at 05-081-06755 in Moffat County, Colorado. While there, I observed a shut-in location. During this inspection the following possible compliance issues were observed:  
No wellhead sign. See photo 1.  
1 - 1" and 2 - 1/2" steel risers at 40.69028, -107.55062 not LOTO or marked for abandonment. Flowline risers not LO/TO or marked are considered unused equipment. See photo 2.  
Install sign to comply with Rule 210.b by 6/28/2019, comply with Rule 603.f by 5/29/2019.  
A follow up on this site inspection will be conducted to ensure the compliance issues have been corrected to comply with COGCC rules. This is a summary of inspection report 689802725.

**Location**

Overall Good:

**Signs/Marker:**

|                    |                                         |       |            |
|--------------------|-----------------------------------------|-------|------------|
| Type               | WELLHEAD                                |       |            |
| Comment:           | No wellhead sign.                       |       |            |
| Corrective Action: | Install sign to comply with Rule 210.b. | Date: | 06/28/2019 |

**Emergency Contact Number:**

Comment: 1-888-291-8588

Corrective Action:

Date: \_\_\_\_\_

**Good Housekeeping:**

|                    |                                                                                                                                                                      |       |            |
|--------------------|----------------------------------------------------------------------------------------------------------------------------------------------------------------------|-------|------------|
| Type               | UNUSED EQUIPMENT                                                                                                                                                     |       |            |
| Comment:           | 1 - 1" and 2 - 1/2" steel risers at 40.69028, -107.55062 not LOTO or marked for abandonment.<br>Flowline risers not LO/TO or marked are considered unused equipment. |       |            |
| Corrective Action: | Comply with Rule 603.f .                                                                                                                                             | Date: | 05/29/2019 |

Overall Good:

**Spills:**

| Type | Area | Volume |  |  |
|------|------|--------|--|--|
|      |      |        |  |  |

In Containment: No

Comment:

Multiple Spills and Releases?

**Equipment:**

| Type:                       | #   |       | corrective date |
|-----------------------------|-----|-------|-----------------|
| Bird Protectors             |     |       |                 |
| Comment:                    |     |       |                 |
| Corrective Action:          |     | Date: |                 |
| Horizontal Heated Separator | # 1 |       |                 |
| Comment:                    |     |       |                 |
| Corrective Action:          |     | Date: |                 |
| Deadman # & Marked          | # 4 |       |                 |
| Comment:                    |     |       |                 |
| Corrective Action:          |     | Date: |                 |

**Venting:**

Yes/No NO

Comment:

Corrective Action:

Date:

**Flaring:**

|          |  |  |
|----------|--|--|
| Type     |  |  |
| Comment: |  |  |

Corrective Action:

Date:

**Inspected Facilities**

Facility ID: 223391 Type: WELL API Number: 081-06755 Status: SI Insp. Status: SI

**Idle Well**

Purpose:  Shut In  Temporarily Abandoned Reminder: \_\_\_\_\_

Comment:

Corrective Action:  Date: \_\_\_\_\_

**Reclamation - Storm Water - Pit**

**Storm Water:**

| Loc Erosion BMPs | BMP Maintenance | Lease Road Erosion BMPs | Lease BMP Maintenance | Chemical BMPs | Chemical BMP Maintenance | Comment |
|------------------|-----------------|-------------------------|-----------------------|---------------|--------------------------|---------|
|                  |                 |                         |                       |               |                          |         |

Comment:

Corrective Action:

Date: \_\_\_\_\_

**Pits:**  NO SURFACE INDICATION OF PIT

**Attached Documents**

You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

| Document Num | Description       | URL                                                                                                                                                                 |
|--------------|-------------------|---------------------------------------------------------------------------------------------------------------------------------------------------------------------|
| 689802732    | Inspection Photos | <a href="http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4833865">http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4833865</a> |