

**Inspection Photos**  
**Location Name: GREEN MONSTER 12-25**  
**API #: 05-071-09289**  
**INSP. #:695100727**



**PHOTO 1: WELLHEAD**



**PHOTO 2: CURRENT OPERATOR NOT POSTED ON WELL SIGN.**  
**CHANGE OPERATOR NAME TO CURRENT OPERATOR IN**  
**ACCORDANCE WITH RULE 210. CA DATE 7/28/19**

## Inspection Photos

Location Name: GREEN MONSTER 12-25

API #: 05-071-09289

INSP. #:695100727



**PHOTO 3: GRASS/WEEDS TO NORTH OF WELLHEAD HOUSE AROUND TELEMETRY EQUIPMENT IS OVERGROWN. CUT OR REMOVE WEEDS IN ACCORDANCE WITH 603. SERIES RULES. CA DATE 6/28/19**



**PHOTO 4: GRASS/WEEDS ON NORTH SIDE OF LOCATIO AROUND ELECTRIC PANEL/METER IS OVERGROWN. CUT OR REMOVE WEEDS IN ACCORDANCE WITH 603. SERIES RULES. CA DATE 6/28/19**



**COLORADO**  
Oil & Gas Conservation  
Commission  
Department of Natural Resources



**Inspection Photos**  
**Location Name: GREEN MONSTER 12-25**  
**API #: 05-071-09289**  
**INSP. #:695100727**



**PHOTO 5: GRASS/WEEDS ON WEST SIDE OF LOCATIO  
AROUND METER HOUSE IS OVERGROWN. CUT OR REMOVE  
WEEDS IN ACCORDANCE WITH 603. SERIES RULES. CA DATE  
6/28/19**



**PHOTO 6: GRASS/WEEDS NEAR ENTRANCE OF LOCATIO  
AROUND 2" DRIP IS OVERGROWN. CUT OR REMOVE WEEDS  
IN ACCORDANCE WITH 603. SERIES RULES. CA DATE 6/28/19**



Inspection Photos  
Location Name: GREEN MONSTER 12-25  
API #: 05-071-09289  
INSP. #:695100727



**PHOTO 7: DRAINAGE DITCH ON ROW JUST EAST OF LOCATION ENTRANCE HAS NO BMP'S OR BMP'S OR INADEQUATE. REPAIR OR INSTALL BMP'S TO PREVENT EROSION IN ACCORDANCE WITH 1002 SERIES RULES. CA DATE 6/28/19.**



**PHOTO 8: DRAINAGE DITCH ON ROW FURTHER EAST OF LOCATION ENTRANCE HAS NO BMP'S OR BMP'S OR INADEQUATE. REPAIR OR INSTALL BMP'S TO PREVENT EROSION IN ACCORDANCE WITH 1002 SERIES RULES. CA DATE 6/28/19.**



**Inspection Photos**  
**Location Name: GREEN MONSTER 12-25**  
**API #: 05-071-09289**  
**INSP. #:695100727**



**PHOTO 9: DRAINAGE DITCH ON ROW EAST/SOUTHEAST OF LOCATION ENTRANCE HAS NO BMP'S OR BMP'S OR INADEQUATE. REPAIR OR INSTALL BMP'S TO PREVENT EROSION IN ACCORDANCE WITH 1002 SERIES RULES. CA DATE 6/28/19.**



**PHOTO 8: DRAINAGE DITCH ON ROW SOUTH OF LOCATION ENTRANCE HAS NO BMP'S OR BMP'S OR INADEQUATE. REPAIR OR INSTALL BMP'S TO PREVENT EROSION IN ACCORDANCE WITH 1002 SERIES RULES. CA DATE 6/28/19.**