

Inspection Photos

Location Name: Clough Production Pit 44-16-694

Location ID 421192, Pit Facility ID 414560



Location 421192. OGCC Pit Number should read 414560.



Gates open at time of inspection.

Inspection Photos

Location Name: Clough Production Pit 44-16-694

Location ID 421192, Pit Facility ID 414560



Manifold system cribbed with wood blocks, unused equipment, flow line directly on pit liner



Manifold system cribbed with wood blocks, unused equipment.

Inspection Photos

Location Name: Clough Production Pit 44-16-694

Location ID 421192, Pit Facility ID 414560



Unused equipment. Flow meter supported by wood blocks.



Gap in netting around pipe penetration.



COLORADO
Oil & Gas Conservation
Commission
Department of Natural Resources

Inspection Photos

Location Name: Clough Production Pit 44-16-694

Location ID 421192, Pit Facility ID 414560



Staining/discolored gravel by 5-gallon pail.



Staining/discolored gravel by 5-gallon pail.

Inspection Photos

Location Name: Clough Production Pit 44-16-694

Location ID 421192, Pit Facility ID 414560



Lines directly on the pit liner. Gaps in net around pipeline penetrations. Gravel migration into the pit.



View is south to south east on western side of the pit.



COLORADO
Oil & Gas Conservation
Commission
Department of Natural Resources

Inspection Photos

Location Name: Clough Production Pit 44-16-694

Location ID 421192, Pit Facility ID 414560



View is to the north to northwest. Four strand wire fence.
Fire lane and buffer lane absent.



Sediment trap located at the southwest corner of the pit.
Gaps in fence below gate and at gate closure.



COLORADO
Oil & Gas Conservation
Commission
Department of Natural Resources

InspectionPhotos
Location Name: Clough Production Pit 44-16-694
Location ID 421192, Pit Facility ID 414560



Gap in fence at pipeline penetration and sediment encroaching towards pit.



Sediment encroaching towards pit. Metal debris.

Inspection Photos

Location Name: Clough Production Pit 44-16-694

Location ID 421192, Pit Facility ID 414560



Vegetation in netting and netting repair.



Sediment encroaching towards pit.

Inspection Photos

Location Name: Clough Production Pit 44-16-694

Location ID 421192, Pit Facility ID 414560



Sediment encroaching towards pit. Gaps in netting.



Looking north to northwest. Rock migration toward pit from adjacent hill side.



COLORADO
Oil & Gas Conservation
Commission
Department of Natural Resources

Inspection Photos

Location Name: Clough Production Pit 44-16-694

Location ID 421192, Pit Facility ID 414560



Sediment migration toward pit. Fire lane and buffer lane absent.



Sediment migration into pit, "T" post potentially penetrating liner near anchor trench.

Inspection Photos

Location Name: Clough Production Pit 44-16-694

Location ID 421192, Pit Facility ID 414560



Erosional rills and failed BMPs (apparent storm water with sediment migration beneath straw bails).



Erosional rills and evidence of livestock inside of fence.

Inspection Photos

Location Name: Clough Production Pit 44-16-694

Location ID 421192, Pit Facility ID 414560



Sampler and wire anchor pin inside of pit complex.



Hose directly on pit liner. Cam lock appears to have been taped.

Inspection Photos

Location Name: Clough Production Pit 44-16-694

Location ID 421192, Pit Facility ID 414560



Two to three foot gap in fence/netting, hose directly on pit liner.



Erosional rills and recently replaced BMPs.



Inspection Photos

Location Name: Clough Production Pit 44-16-694

Location ID 421192, Pit Facility ID 414560



Hose and wood blocks on pit liner.



Excess equipment near manifold area. Rope safety line on liner and rescue buoy located on the outside of the netted pit.

Inspection Photos

Location Name: Clough Production Pit 44-16-694

Location ID 421192, Pit Facility ID 414560



Excess equipment near manifold area.



Gravel discoloration and appears to be a drip from the pipe with plastic sheeting and duct tape. Unused equipment between concrete supports.



COLORADO
Oil & Gas Conservation
Commission
Department of Natural Resources

Inspection Photos

Location Name: Clough Production Pit 44-16-694

Location ID 421192, Pit Facility ID 414560



Straw bails just off of Location near entrance to the Pit Facility.



Pipe on pit liner. Yellow rope secured around poly pipe line.



COLORADO
Oil & Gas Conservation
Commission
Department of Natural Resources

Inspection Photos

Location Name: Clough Production Pit 44-16-694

Location ID 421192, Pit Facility ID 414560



Tracer wire with stake on the ground.



Entrance to Pit Facility open. Note used straw bails just off of Location.