

**FORM
INSP**Rev
X/15**State of Colorado
Oil and Gas Conservation Commission**1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109

Inspection Date:

05/14/2019

Submitted Date:

05/29/2019

Document Number:

690101247**FIELD INSPECTION FORM**
 Loc ID 318013 Inspector Name: Maclaren, Joe On-Site Inspection ☐ 2A Doc Num:
Operator Information:OGCC Operator Number: 47120Name of Operator: KERR MCGEE OIL & GAS ONSHORE LPAddress: P O BOX 173779City: DENVER State: CO Zip: 80217-**Status Summary:**

- ☐ THIS IS A FOLLOW UP INSPECTION
- ☐ FOLLOW UP INSPECTION REQUIRED
- ☐ NO FOLLOW UP INSPECTION REQUIRED

Findings:3 Number of Comments0 Number of Corrective Actions☐ Corrective Action Response Requested**ANY CORRECTIVE ACTION(S) FROM
PREVIOUS INSPECTIONS THAT HAVE NOT
BEEN ADDRESSED ARE STILL APPLICABLE****Contact Information:**

Contact Name	Phone	Email	Comment
Schlagenhauf, Mark		mark.schlagenhauf@state.co.us	
		cogccinspections@anadarko.com	

Inspected Facilities:

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
240395	WELL	PR	03/01/2019	GW	123-08183	ADAM GABEL GAS UNIT 1	EG
464073	OFF-LOCATION FLOWLINE	AC	04/29/2019		-	Wellhead Line 8SWNE	EG
464353	SPILL OR RELEASE	AC	05/14/2019		-	Adam Gabel Gas Unit 1	EG

General Comment:

Engineering Integrity inspection performed on May 14th, 2019 in response to initial form 19 spill report Doc #402041593 received by COGCC on 05/10/2019 that outlines: During reclamation activities at the decommissioned Adam Gabel Gas Unit #1 tank battery facility, historical petroleum hydrocarbon impacts were encountered. Details of observations made during this field inspection are located in the flowline and comment sections of this report. Photos uploaded.

Inspected Facilities

Facility ID: 240395 Type: WELL API Number: 123-08183 Status: PR Insp. Status: EG

Facility ID: 464073 Type: OFF- API Number: - Status: AC Insp. Status: EG

Flowline

#1	Type:	of Lines
----	-------	----------

Flowline Description

Flowline Type: _____ Size: _____ Material: _____
 Variance: _____ Age: _____ Contents: _____

Integrity Summary

Failures: _____ Spills: _____ Repairs Made: _____
 Coatings: _____ H2S: _____ Cathodic Protection: _____

Pressure Testing

Witnessed: _____ Test Result: _____ Charted: _____

COGCC Rules(check all that apply)

☐ 1101. Installation and Reclamation ☐ 1102. Operations, Maintenance, and Repair ☒ 1103. Abandonment

Comment: Well has been plugged and abandoned; COGCC form 42 notice of start of plugging operations Doc #401965351 received on 03/08/2019. No flowline risers were observed on location (facility or PA wellhead). COGCC form 42 notice of flowlines abandoned Doc #402015747 was received on 04/22/2019. All tanks and equipment at facility/ battery have been removed. Anadarko contractors on location are in the process of removing impacted soils (historical).

Corrective Action: _____

Date: _____

Facility ID: 464353 Type: SPILL OR API Number: - Status: AC Insp. Status: EG

COGCC Comments

Comment	User	Date
As outlined in CA section of supplemental form 19 Doc #402041593: During reclamation activities at the decommissioned Adam Gabel Gas Unit #1 tank battery facility, historical petroleum hydrocarbon impacts were encountered. The volume of the release is unknown. The Kerr-McGee facility will be deconstructed. The excavation will be restored to its pre-release grade.	maclarej	05/29/2019

Attached Documents

You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
690101249	View (NW) of remediation work at facility	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4834680
690101250	View (W) of decommissioned facility and PA well	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4834681