

Inspection Photos
Operator: BP America
Location/API #: 067-06753
Date: 5-23-2319



Photo 1. View of erosional scouring around cobble run-down and facilities within the southeastern project area.



Photo 2. View of musk thistle (*Carduus nutans*) rosettes within the interim reclamation area.



Photo 3. View of erosional channel forming within the eastern project area.