

**FORM
INSP**Rev
X/15**State of Colorado
Oil and Gas Conservation Commission**1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109

Inspection Date:

05/29/2019

Submitted Date:

05/29/2019

Document Number:

693500183**FIELD INSPECTION FORM**
 Loc ID 335576 Inspector Name: Silver, Randy On-Site Inspection ☐ 2A Doc Num: _____
Operator Information:OGCC Operator Number: 10633Name of Operator: CRESTONE PEAK RESOURCES OPERATING LLCAddress: 1801 CALIFORNIA STREET #2500City: DENVER State: CO Zip: 80202**Status Summary:**

- ☐ THIS IS A FOLLOW UP INSPECTION
- ☐ FOLLOW UP INSPECTION REQUIRED
- ☒ NO FOLLOW UP INSPECTION REQUIRED

Findings:15 Number of Comments0 Number of Corrective Actions☐ Corrective Action Response Requested**ANY CORRECTIVE ACTION(S) FROM
PREVIOUS INSPECTIONS THAT HAVE NOT
BEEN ADDRESSED ARE STILL APPLICABLE****Contact Information:**

Contact Name	Phone	Email	Comment
,		Cogcc.inspections@crestone pr.com	ALL INSPECTIONS

Inspected Facilities:

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
329	WELL	PR	08/01/2008	GW	013-06572	LUMRY 32-24	PR
330	WELL	PR	07/01/2017	GW	013-06573	LUMRY 8-2-24	PR
331	WELL	PR	06/30/2008	GW	013-06574	LUMRY 42-24	PR
332	WELL	PR	02/06/2008	GW	013-06575	LUMRY 6-4-24	PR
333	WELL	PR	06/24/2008	GW	013-06576	LUMRY 31-24	PR
343	WELL	PR	07/01/2017	GW	013-06577	LUMRY 6-0-24	PR
206687	WELL	PR	06/25/1985	GW	013-06182	LUMRY G UNIT 1	PR

General Comment:

LocationOverall Good: ☒

Signs/Marker:			
Type	WELLHEAD		
Comment:	Adequate		
Corrective Action:		Date:	
Type	BATTERY		
Comment:	Adequate		
Corrective Action:		Date:	
Type	TANK LABELS/PLACARDS		
Comment:	Adequate		
Corrective Action:		Date:	

Emergency Contact Number:

Comment:

Corrective Action:

Date: _____

Overall Good: ☒

Spills:			
Type	Area	Volume	

In Containment: No

Comment:

☐ Multiple Spills and Releases?

Fencing/:			
Type	TANK BATTERY		
Comment:	Steel rod		
Corrective Action:		Date:	
Type	SEPARATOR		
Comment:	Steel rod		
Corrective Action:		Date:	
Type	WELLHEAD		
Comment:	Steel rod		
Corrective Action:		Date:	

Venting:

Yes/No	NO		
Comment:			
Corrective Action:		Date:	

Flaring:

Type		
Comment:		
Corrective Action:		Date:

Inspected Facilities						
Facility ID:	329	Type:	WELL	API Number: 013-06572	Status: PR	Insp. Status: PR
Producing Well						
Comment:	PR					
Corrective Action:						Date:
Facility ID:	330	Type:	WELL	API Number: 013-06573	Status: PR	Insp. Status: PR
Producing Well						
Comment:	PR					
Corrective Action:						Date:
Facility ID:	331	Type:	WELL	API Number: 013-06574	Status: PR	Insp. Status: PR
Producing Well						
Comment:	PR					
Corrective Action:						Date:
Facility ID:	332	Type:	WELL	API Number: 013-06575	Status: PR	Insp. Status: PR
Producing Well						
Comment:	PR					
Corrective Action:						Date:
Facility ID:	333	Type:	WELL	API Number: 013-06576	Status: PR	Insp. Status: PR
Producing Well						
Comment:	PR					
Corrective Action:						Date:
Facility ID:	343	Type:	WELL	API Number: 013-06577	Status: PR	Insp. Status: PR
Producing Well						
Comment:	PR					
Corrective Action:						Date:
Facility ID:	206687	Type:	WELL	API Number: 013-06182	Status: PR	Insp. Status: PR
Producing Well						
Comment:	PR					
Corrective Action:						Date:

Reclamation - Storm Water - Pit**Storm Water:**

Loc Erosion BMPs	BMP Maintenance	Lease Road Erosion BMPs	Lease BMP Maintenance	Chemical BMPs	Chemical BMP Maintenance	Comment
Gravel	Pass	Gravel	Pass			

Comment: Corrective Action: Date: **Pits:** ☐ NO SURFACE INDICATION OF PIT**COGCC Comments**

Comment	User	Date
Routine inspection	silverr	05/29/2019

Attached DocumentsYou can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
693500184	loc pic	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4834792