

Location

Overall Good:

Signs/Marker:

Type	TANK LABELS/PLACARDS		
Comment:	PHOTO 4: NO NFPA SIGNS POSTED ON PRODUCED WATER TANK.		
Corrective Action:	Install sign to comply with Rule 210.d.	Date:	07/20/2019
Type	OTHER		
Comment:	The Qtr-Qtr of the Keiko 14-6 is SESW and the Qtr-Qtr of the Keiko 14-6 TR is SWSW on the lease signs. The Lot to the West is not a true 40 acres. I believe that the correct Qtr-Qtr for both wells is SESW. The footages also don't reflect this. The AS Drilled : Lat/Long on both well might reflect this.		
Corrective Action:	Pioneer needs to investigate and possibly correct the Lease sign on the Keiko 14-6 TR (05-071-8629) well to SESW. Contact (COGCC)Dennis Ahlstrand : 303-894-2100, xt 5116 of any changes. CA FROM LAST INSPECTION NOT ADDRESSED DOC #687902080	Date:	06/30/2018

Emergency Contact Number:

Comment:	<input type="text"/>	Date:	<input type="text"/>
Corrective Action:	<input type="text"/>		

Overall Good:

Spills:

Type	Area	Volume			

In Containment: No

Comment:

Multiple Spills and Releases?

Equipment:

Type: Ancillary equipment	# 2		corrective date
Comment:	TELEMETRY EQUIPMENT		
Corrective Action:		Date:	
Type: Bradenhead	# 2		
Comment:	IS PLUMBED TO SURFACE		
Corrective Action:		Date:	

Tanks and Berms:

Contents	#	Capacity	Type	Tank ID	SE GPS
PRODUCED WATER	1	500 BBLS	STEEL AST		
Comment:	<input type="text"/>				
Corrective Action:	<input type="text"/>				Date:

Paint

Condition	Adequate
Other (Content)	<input type="text"/>
Other (Capacity)	<input type="text"/>
Other (Type)	<input type="text"/>

Berms				
Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance
	Inadequate	Walls Insufficient	Base Insufficient	Inadequate
Comment:	PHOTO 5: NO BERMS AROUND PRODUCED WATER TANK.			
Corrective Action:	Repair or install berms or other secondary containment devices per Rule 605. CA FROM PREVIOUS INSPECTION DOC #687902080			Date: 06/30/2018

Venting:

Yes/No	NO		
Comment:			
Corrective Action:		Date:	

Flaring:

Type		
Comment:		
Corrective Action:		Date:

Inspected Facilities

Facility ID: 273233 Type: WELL API Number: 071-08150 Status: PR Insp. Status: PR

Producing Well

Comment:

Corrective Action:

Date:

Facility ID: 281717 Type: WELL API Number: 071-08629 Status: PR Insp. Status: PR

Producing Well

Comment:

Corrective Action:

Date:

Reclamation - Storm Water - Pit

Storm Water:

Loc Erosion BMPs	BMP Maintenance	Lease Road Erosion BMPs	Lease BMP Maintenance	Chemical BMPs	Chemical BMP Maintenance	Comment

Comment:

Corrective Action:

Date: _____

Pits: NO SURFACE INDICATION OF PIT

COGCC Comments

Comment	User	Date
THIS IS A FOLLOWUP INSPECTION TO INSPECTION DOC#687902080. CORRECTIVE ACTIONS HAVE NOT BEEN ADDRESS AND THERE IS AN ADDITIONAL CORRECTIVE ACTION AT TIME OF THIS INSPECTION THAT WAS NOT NOTED ON PREVIOUS INSPECTION (SEE TANKS LABELS/PLACARDS SECTION OF THIS INSPECTION).	beardslt	05/20/2019

Attached Documents

You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
402054603	INSPECTION SUBMITTED	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4831343
695100652	LCATION PHOTOS	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4831310