

**FORM  
INSP**

Rev  
X/15

**State of Colorado  
Oil and Gas Conservation Commission**

1120 Lincoln Street, Suite 801, Denver, Colorado 80203  
Phone: (303) 894-2100 Fax: (303) 894-2109



Inspection Date:

05/23/2019

Submitted Date:

05/23/2019

Document Number:

695100698

**FIELD INSPECTION FORM**

Loc ID 309546 Inspector Name: Beardslee, Tom On-Site Inspection  2A Doc Num: \_\_\_\_\_

**Operator Information:**

OGCC Operator Number: 10672  
Name of Operator: TIMBER CREEK OPERATING LLC  
Address: 1001 17TH STREET #1000  
City: DENVER State: CO Zip: 80202

**Status Summary:**

- THIS IS A FOLLOW UP INSPECTION
- FOLLOW UP INSPECTION REQUIRED
- NO FOLLOW UP INSPECTION REQUIRED

**Findings:**

- 6 Number of Comments
- 1 Number of Corrective Actions
- Corrective Action Response Requested

**ANY CORRECTIVE ACTION(S) FROM PREVIOUS INSPECTIONS THAT HAVE NOT BEEN ADDRESSED ARE STILL APPLICABLE**

**Contact Information:**

Contact Name	Phone	Email	Comment
Mack, Ronald		ronaldmack@tcenergy.us	<a href="#">All Inspections</a>
Santistevan, Vince	719-845-2102/719-680-9705	vincasantistevan@tcenergy.us	<a href="#">All Inspections</a>

**Inspected Facilities:**

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
299638	WELL	PR	09/10/2012	GW	071-09678	APACHE CANYON 09-06	PR

**General Comment:**

**Location**

Overall Good:

Emergency Contact Number:

Comment:

Corrective Action:

Date: \_\_\_\_\_

Overall Good:

**Spills:**

Type	Area	Volume			

In Containment: No

Comment:

Multiple Spills and Releases?

**Equipment:**

Type	Area	Volume	Comment	Corrective Action	Date	corrective date
Type: Gas Meter Run		# 1				
Comment:						
Corrective Action:						Date:
Type: Compressor		# 1				
Comment:	PHOTO 3: Vacuum pump observed on well without COGCC approval.					
Corrective Action:	Provide COGCC with documentation showing approval of use of vacuum pump.					Date: <u>06/08/2019</u>
Type: Vertical Separator		# 1				
Comment:						
Corrective Action:						Date:
Type: Progressive Cavity		# 1				
Comment:						
Corrective Action:						Date:
Type: Other		# 2				
Comment:	PRODUCED WATER CONTAINERS					
Corrective Action:						Date:
Type: Bradenhead		# 1				
Comment:	IS PLUMBED TO SURFACE					
Corrective Action:						Date:
Type: Ancillary equipment		# 1				
Comment:	TELEMETRY EQUIPMENT					
Corrective Action:						Date:
Type: Prime Mover		# 1				
Comment:						
Corrective Action:						Date:

**Venting:**

Yes/No	NO		
Comment:			

Corrective Action:		Date:	
--------------------	--	-------	--

**Flaring:**

Type			
Comment:			
Corrective Action:		Date:	

**Inspected Facilities**

Facility ID: 299638 Type: WELL API Number: 071-09678 Status: PR Insp. Status: PR

**Producing Well**

Comment:

Corrective Action:

Date:

**Reclamation - Storm Water - Pit**

**Storm Water:**

Loc Erosion BMPs	BMP Maintenance	Lease Road Erosion BMPs	Lease BMP Maintenance	Chemical BMPs	Chemical BMP Maintenance	Comment

Comment:

Corrective Action:

Date: \_\_\_\_\_

**Pits:**     NO SURFACE INDICATION OF PIT

**Attached Documents**

You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
402054616	INSPECTION SUBMITTED	<a href="http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4831356">http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4831356</a>
695100699	LOCATION PHOTOS	<a href="http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4831331">http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4831331</a>