

Location

Overall Good:

Emergency Contact Number:

Comment:

Corrective Action:

Date: _____

Good Housekeeping:

Type

OTHER

Comment:

PHOTO 3: OIL POOLING IN COMPRESSOR SKID.
PHOTO 4: OIL POOLING IN PRIME MOVER SKID.

Corrective Action:

Increase frequency of maintenance and self inspection schedule of equipment to prevent impacting surface materials and mixing of wastes with precipitation" Comply with general provisions of the oil and gas act for wildlife protection.

Date: 06/23/2019

Overall Good:

Spills:

Type

Area

Volume

In Containment: No

Comment:

Multiple Spills and Releases?

Equipment:

corrective date

Type: Compressor

1

Comment:

PHOTO 5: Vacuum pump observed on well without COGCC approval. Provide COGCC with documentation showing approval of use of vacuum pump. CA DATE 6/8/19

Corrective Action:

Provide COGCC with documentation showing approval of use of vacuum pump.

Date: 06/08/2019

Venting:

Yes/No

NO

Comment:

Corrective Action:

Date:

Flaring:

Type

Comment:

Corrective Action:

Date:

Inspected FacilitiesFacility ID: 282649 Type: WELL API Number: 071-08687 Status: PR Insp. Status: PR**Producing Well**Comment: Corrective Action: Date: **Attached Documents**You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
402054617	INSPECTION SUBMITTED	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4831357
695100708	LOCATION PHOTOS	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4831335