

Location

Overall Good:

Signs/Marker:

Type OTHER

Comment: [Fracing Adequate](#)

Corrective Action:

Date:

Emergency Contact Number:

Comment:

Corrective Action:

Date: _____

Overall Good:

Spills:

Type	Area	Volume

In Containment: No

Comment:

Multiple Spills and Releases?

Fencing/:

Type LOCATION

Comment: [Sound walls on 3 sides](#)

Corrective Action:

Date:

Venting:

Yes/No NO

Comment:

Corrective Action:

Date:

Flaring:

Type

Comment:

Corrective Action:

Date:

Inspected Facilities

Facility ID: 456592 Type: WELL API Number: 123-47580 Status: DG Insp. Status: DG

Well Stimulation

Stimulation Company: Halliburton Stimulation Type: HYDRAULIC FRAC
Other: _____

Observation:

Maximum Casing Recorded: 7839 PSI Tubing: _____
Surface: _____ Intermediate: _____
Production: _____ Instantaneous Shut-In Pressure (ISIP) _____
Bradenhead Psi: 122 Frac Flow Back: Fluid: _____ Gas: _____

Comment: _____

Corrective Action: _____ Date: _____

Completion

Operation: _____
Date Flowback: _____
Contractor: _____
Comment: _____
Corrective Action: _____ Date: _____

Reclamation - Storm Water - Pit

Storm Water:

Loc Erosion BMPs	BMP Maintenance	Lease Road Erosion BMPs	Lease BMP Maintenance	Chemical BMPs	Chemical BMP Maintenance	Comment
Ditches	Pass					
Berms	Pass	Gravel	Pass			

Comment:

Corrective Action:

Date: _____

Pits: NO SURFACE INDICATION OF PIT

COGCC Comments

Comment	User	Date
Routine inspection	silverr	05/30/2019

Attached Documents

You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
693500199	loc pic	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4835816